

Work Order

Work Order 448585 Accident right view mirror damaged (61846)
Created By WONGKOC@SBSTRANSIT.COM.SG
Created 05-APR-2023

Scheduled Start 05-APR-2023
Date
Scheduled End Date 05-APR-2023
Status Assigned

Reprint

WO Type BRKD
Breakdown
Department BB
Bukit Batok Workshop
PM Schedule
Cost Code
Problem Code
Project
Standard WO

Parent WO
Class
Priority
Warranty
Safety
Equipment Criticality
Assigned To BBVENDA6
Reported By 133784
Assigned By
Multiple Equipment No
Campaign
Campaign Event
Date Started
Date Completed
Time Completed

Equipment

Equipment SBS8760M
BBBE
BB
SBSB
Manufacturer
Model WFF2
Serial Number YS2K4X20001865364
Location

Scania KUB4X2(EEV), SD, AC, 2 Axle
BB Bus & Bus Equipment
BUKIT BATOK WORKSHOP
SBS TRANSIT

Reliability Ranking
Reliability Ranking Index

Reliability Ranking Score

WO/PM Comments

WONGKOC@SBSTRANSIT.COM.SG [05-APR-2023 08:12]:

Date/Time: 04/04/2023 @ 0730hrs, SVC: 100, Location: Along Commonwealth Ave West towards GMT, Third party: TT SMB3509R, Brake effective: Effective

WONGKOC@SBSTRANSIT.COM.SG [05-APR-2023 14:49]:

Accident happened on 05/04/2023

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

<<SBS TRANSIT LTD-BUS ENGINEERING>>

email: rasul@lkkauto.com