

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Not Assembled
11 Days @
Assembly After Paint
6 days

Vehicle Number : SLX1695U

Vehicle Model : HYUNDAI ELANTRA

Chassis Number : KMHDH41CMCU171822

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID <i>Br ✓</i>	1	\$
2	BOOT LID LOGO <i>new</i>	1	\$
3	BOOT LID HINGES (LH & RH) <i>Br ✓</i>	2	\$
4	BOOT LID LOCK <i>new</i>	1	\$
5	BOOT LID LOGO <i>new</i>	1	\$
6	BOOT LID INNER TRIM <i>?</i>	1	\$
7	BOOT LID INNER TRIM CLIPS <i>new</i>	10	\$
8	BOOT LID LAMP (LH & RH) <i>old car light NIS ?</i>	2	\$
9	BOOT LID WEATHERSTRIP <i>dimen 50cm</i>	1	\$
10	TAIL LAMP (LH & RH) <i>old car light NIS ?</i>	2	\$
11	TAIL LAMP SIDE COVER (LH & RH) <i>old car light</i>	2	\$
12	REAR FENDER (LH & RH) <i>R X</i>	2	\$
13	REAR BUMPER <i>Br ✓</i>	1	\$
14	REAR BUMPER CLIPS <i>new</i>	10	\$
15	REAR BUMPER RETAINER (LH & RH) <i>new</i>	2	\$
16	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$
17	REAR BUMPER REINFORCEMENT BRACKET (LH & RH) <i>R X</i>	2	\$
18	REAR BUMPER REFLECTOR (LH & RH) <i>new</i>	2	\$
19	END PANEL <i>?</i>	1	\$
20	END PANEL UPPER GARNISH <i>?</i>	1	\$
21	END PANEL UPPER GARNISH CLIPS <i>?</i>	10	\$
22	SPARE TYRE TANK <i>R X</i>	1	\$
23	SPARE TYRE TANK UPPER BOARD <i>new</i>	1	\$
24	REAR SPLASH SHIELD (LH & RH) <i>new</i>	2	\$
25	REAR SPLASH SHIELD CLIPS (LH & RH) <i>new</i>	30	\$

Reverse Camera *?*

Number plate light (2pcs) *?*

Boot lid switch *?*

Discount Less 20%
List Prices Total

S/N	Special Nett Items:	Qty	
1	REVERSE SENSOR <i>new</i>	1 SET	\$
2	REAR NUMBER PLATE WITH HOLDER <i>old</i>	1 SET	\$

Special Nett Total

\$

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLX1695U

Vehicle Model : HYUNDAI ELANTRA

Chassis Number : KMHDH41CMCU171822

S/N	Labour Descriptions	Charges	
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE	\$ 1800.00	700
2	TO SPRAY PAINTING ON: BOOT LID, REAR BUMPER, REAR LH & RH FENDER, SPARE TYRE TANK, END PANEL.	\$ 1800.00	1000
3	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$ 280.00	7
4	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO BOOT LID & TEST FUNCTION	\$ 200.00	50
5	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION	\$ 150.00	50
6	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$ 150.00	20
7	TO REMOVE & INSTALL BOOT LID COMPARTMENTS ATTACHMENTS, TRIMMINGS & FITTINGS TO ENABLE REPAIRS.	\$ 200.00 200.00	60

Labour Total \$ 4580.00

Parts & Labour Total \$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: