

Name & Address:

Motor Claims Department

ALLIANZ INSURANCE (S) PTE LTD

79 ROBINSON ROAD #09-01

SINGAPORE 068897

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

YEAR MODEL:

30/07/2020

Vehicle No:

SMU1785Y

Brand & Model:

MINI Cooper Hatch RHD

Chassis/VIN No:

WMWXR320X02N11722

WIP#:

11303

Date:

8-Apr-23

Franchise:

MINI

Contact Person (Eurokars):

ERIC

Contact No (Eurokars):

6331 0697

REPAIR ESTIMATE

PARTS / MATERIAL CHARGES							MARK = Survey Marking [Key "A" if item is approved]	
NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE		
1	REAR FENDER ARCH LH <i>cut /</i>	M51.77.7.300.821	1		-	\$ 200.20		
2	REAR BUMPER LOWER SPOILER <i>sun /</i>	M51.12.7.380.015	1		-	\$ 284.00		
3	SENSOR GASKET <i>re /</i>	B66.20.9.283.203	4		-	\$ 27.56		
4	LIGHT ALLOY RIM REAR LH <i>sun /</i>	M36.11.6.855.109	1		-	\$ 1,054.11		
5	RUBBER VALVE <i>re /</i>	B36.12.1.116.326	1		-	\$ 9.62		
6	VALVE <i>m /</i>	B36.14.1.095.389	1		-	\$ 6.89		
7						\$ -		

Sub-Total (Parts Price) \$ - \$ 1,582.38

LABOUR / SERVICES CHARGES				REVISED	PRICE
NO	DESCRIPTION				
1	TO REMOVE /REPLACE ACCIDENT DAMAGED BODY PARTS. TO REPAIR REAR FENDER LH ALL AREAS AFFECTED BY THE ACCIDENT.			1680	\$ 2,100.00
2	TO RESPRAY REAR FENDER LH, REAR BUMPER			1600	\$ 2,000.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			150	\$ 250.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.			nett	\$ 120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.			nett	\$ 680.00
6	TO SUPPLY / INSTALL THE REAR FENDER LH STICKER.			nett	\$ 270.00
7	TO TRANSFER THE REVERSE SENSORS.			nett	\$ 150 300.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150	\$ 250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			nett	\$ 250 250.00
10	SUNDRIES.			nett	\$ 20 50.00

Survey Date & Time:

Repair Days:

Excess:

Sub-Total (Labour Price) \$ - \$ 6,370.00

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

REPAIR ESTIMATE

	REVISED	PRICE
Parts Price	\$ -	\$ 1,582.38
Labour Price	\$ -	\$ 6,370.00
Total (Initial Estimate)	\$ -	\$ 7,952.38
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 7,952.38
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 7,952.38
GST 8%	\$ -	\$ 636.19
GRAND TOTAL	\$ -	\$ 8,588.57

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL
 4p 90010068
 6 days
 11/04/23 @ 1010
 Repair after repair