

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 11 Apr 2023

**Preliminary Advice**

Vehicle No	: SLM5365D	Accident Date	: 06/04/2023
Make	: NISSAN QASHQAI	Policy No.	: SP2002718378-01
Assignment Date	: 06/04/2023	Excess	: S\$600.00
Date of Inspection	: 11/04/2023	Est. Duration of Repair	: 4
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) BLK 8 DEFU SOUTH STREET 1, DEFU INDUSTRIAL CITY #04-29 SINGAPORE 533758		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,590.50
Revised Amount	:S\$	2,133.50
Check Items (Estimated)	:S\$	605.00
Total	:S\$	2,738.50

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	29,059.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,941.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO SECOND HAND PARTS AVAILABLE.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.