

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ANGELA LIM XIUYAN
BLK 407 PANDAN GARDENS #13-50
SINGAPORE 600407

Contact : 86926881, 86926880

TAX INVOICE

Repair Code : CLM17701

Date in : 10/04/2023

Vehicle Num. : SJK5423D

Model : HONDA AIRWAVE 1.5M CVT ABS D/AIRBAG 2WD 5DR

Chassis/Eng# : GJ11305723/L15A5206989

Tip Grab
Xiao Tony

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Distorted</i>	1	985.00	✓ 985.00
REAR BUMPER INNER SIDE SHIELD L/R <i>new</i>	2	88.00	+ 176.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	32.50	✓ 65.00
REAR BUMPER TOP BEAM <i>Best</i>	1	125.80	✓ 125.80
REAR END PANEL <i>Dealed</i>	1	508.40	✓ 508.40
REAR END PANEL INNER TOP GARNISH <i>Dealed</i>	1	148.00	✓ 148.00
REAR END PANEL LOCK STRIKER <i>new</i>	1	26.70	+ 26.70
REAR EXHAUST SILENCER	1	585.00	+ 585.00
REAR EXHAUST SILENCER GASKET KIT	1	32.00	+ 32.00
REAR EXHAUST SILENCER RUBBER MOUNTING	2	22.00	+ 44.00
REAR FENDER INNER TRIM COVER L/R <i>cracked</i>	2	412.20	✓ 824.40
REAR NUMBER PLATE LAMP L/R <i>new</i>	2	42.30	+ 84.60
REAR SPARE TYRE PANEL <i>Regis</i>	1	1210.00	+ 1,210.00
REAR SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD <i>new</i>	1	301.70	+ 301.70
REAR TAILGATE <i>Dealed</i>	1	1382.50	1232 ✓ 1,382.50
REAR TAILGATE DAMPER L/R <i>new</i>	2	198.60	+ 397.20
REAR TAILGATE EMBLEM <i>new</i>	1	46.20	✓ 46.20
REAR TAILGATE HINGES L/R <i>new</i>	2	87.40	+ 174.80

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ANGELA LIM XIUYAN
BLK 407 PANDAN GARDENS #13-50
SINGAPORE 600407

Contact : 86926881, 86926880

TAX INVOICE

Repair Code : CLM17701

Date in : 10/04/2023

Vehicle Num. : SJK5423D

Model : HONDA AIRWAVE 1.5M CVT ABS D/AIRBAG 2WD 5DR

Chassis/Eng# : GJ11305723/L15A5206989

REAR TAILGATE INNER HANDLE GARNISH	Rehd	1	53.90	✓	53.90
REAR TAILGATE INNER TRIM BOARD	cnhd	1	225.00	✓	225.00
REAR TAILGATE LOGO	neu	1	33.10	✓	33.10
REAR TAILGATE MECHANISM LOCK	Dnd	1	109.00	✓	109.00
REAR TAILGATE OUTER CHROME GARNISH	cnhd	1	288.90	✓	288.90
REAR TAILGATE OUTER GARNISH	Rehd	1	451.50	✓	451.50
REAR TAILGATE OUTER LOCK HANDLE	neu	1	53.40	+	53.40
REAR TAILGATE REFLECTOR LAMP L/R	LH cnhd	2	245.30	✓	490.60
REAR TAILGATE RUBBER GUIDE STOPPER L/R	neu	2	18.50	+	37.00
REAR TAILGATE WEATHER STRIP	ht	1	192.00	✓	192.00
REAR TAILGATE WINDSCREEN MOULDING	neu	1	88.00	✓	88.00
REAR TAILLAMP L/R	ht	2	258.00	✓	516.00

Subtotal before discount

9,655.70

Percentage discount 20%

1,931.14

Sub-total 1

7,724.56

REAR BUMPER CLIPS - SET	neu	1	50.00	30	50.00
REAR BUMPER INNER SIDE SHIELD CLIPS L/R - SET	neu	2	20.00	+	40.00
REAR BUMPER REVERSE SENSOR	Dnd	1	250.00	200	250.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ANGELA LIM XIUYAN
BLK 407 PANDAN GARDENS #13-50
SINGAPORE 600407

Contact : 86926881, 86926880

TAX INVOICE

Repair Code : CLM17701

Date in : 10/04/2023

Vehicle Num. : SJK5423D

Model : HONDA AIRWAVE 1.5M CVT ABS D/AIRBAG 2WD 5DR

Chassis/Eng# : GJ11305723/L15A5206989

REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>new</i>	1	30.00	<i>20</i>	30.00
REAR END PANEL SEALANT	<i>new</i>	1	80.00	<i>60</i>	80.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	<i>new</i>	2	40.00	<i>60</i>	80.00
REAR NUMBER PLATE	<i>new</i>	1	25.00	<i>+</i>	25.00
REAR NUMBER PLATE HOLDER	<i>new</i>	1	50.00	<i>+</i>	50.00
REAR REVERSE CAMERA	<i>new</i>	1	500.00	<i>+</i>	500.00
REAR SPARE TYRE PANEL INSULATOR MAT	<i>new</i>	1	250.00	<i>+</i>	250.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>new</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE OUTER CHROME GARNISH CLIPS - SET	<i>new</i>	1	30.00	<i>10</i>	30.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	<i>new</i>	1	30.00	<i>20</i>	30.00
REAR TAILGATE WINDSCREEN SEALANT	<i>new</i>	1	60.00	<i>✓</i>	60.00
REAR TAILLAMP CLIPS L/R - SET	<i>new</i>	2	30.00	<i>20</i>	60.00
Subtotal before discount					1,585.00
Percentage discount 0%					0.00
Sub-total 2					1,585.00
Parts-total					9,309.56

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

120 *150.00*

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ANGELA LIM XIUYAN
 BLK 407 PANDAN GARDENS #13-50
 SINGAPORE 600407

Contact : 86926881, 86926880

TAX INVOICE

Repair Code : CLM17701

Date in : 10/04/2023

Vehicle Num. : SJK5423D

Model : HONDA AIRWAVE 1.5M CVT ABS D/AIRBAG 2WD 5DR

Chassis/Eng# : GJ11305723/L15A5206989

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

60 80.00

900 1,200.00

X 100.00

✓ 1,000.00

60 80.00

✓ 80.00

2300

Labour Total

2,770.00

Parts & Labour Total

12,079.56

Adrian Li

h/s 10/04/23.

*** This is a computer-generated document which requires no signature.***

page 4

07 Days

total: 7686

4/s: 6150. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer