



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

China Taiping Insurance (Singapore) Ltd Pte

Date : 10-Apr-23
Attn : MOTOR CLAIMS DEPT

VEHICLE NO. : SLQ3978C
CHASSIS NO. : GM41105537
MAKE / MODEL : Grace Hybrid
DATE OF ACCIDENT: 30-Mar-23
YOUR INSURED VEHICLE NUMBER : SHB5583X

	<u>PARTS DISCRIPTION</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	REAR BOOT		1PC	\$ 835.50	\$ RP 835.50
2	REAR TAILLAMP	LH RH	2PC	\$ RHX 240.00	\$ LH? 480.00
3	REAR BUMPER		1PC	\$ 855.00	\$ de 855.00
4	REAR BUMPER REFLECTOR LENS	LH RH	2PC	\$ 35.00	\$ x 70.00
5	REAR BOOT REFLECTOR LAMP	LH RH	2PC	\$ RMX 312.90	\$ LH? 625.80
6	REAR BUMPER RETAINER	LH RH	2PC	\$ RHX 89.00	\$ LH de 178.00
7	REAR END PANEL		1PC	\$ 580.00	\$ bt 580.00
8	REAR END PANEL TOP COVER/GARNISH		1PC	\$ 120.00	\$ de 120.00
				Total	\$ 3,744.30
				Less 20%	\$ 748.86
				Total	\$ 2,995.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

	<u>SPECIAL NETTS</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	REAR BUMPER CLIPS	1	\$ 40.00	\$ 40.00 Bover
2	REVERSE SENSORS	1	\$ 380.00	\$ 380.00 200mm
			Total	\$ 420.00

	<u>LABOUR CHARGES</u>	
1	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.	\$ 1,000.00 ⁶⁰⁰
2	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	\$ 900.00 ⁶⁰⁰
3	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSOR	\$ 120.00 ³⁰
4	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	\$ 180.00 ^x
		TOTA \$ 2,200.00
		TOTAL PARTS \$ 3,415.44
		GRAND TOTAL \$ 5,615.44

Tan Jiah 97495744 / 62563561
WP 10/4/23 @ 2:15 pm
4/5 Reming after repair 5 days
tan.jiah@lkkauto.com