

(08/11/13) WBS

ASS. REC. BY: LMW

REF:

CC4/AIS 23003659/R pa3

9436

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNH 5982Aat Workshop m/s ETHO 2of 30, BUKET BATAK CRESInsured: AIS

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 126K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 41KVeh No: SNH 5982A Yr Regn: 2022 / NOVType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 3 1.5AT M-Hybrid C.c. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 2950 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BP 2S 4AP 1151566Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 05/04/23Survey held at ETHO 2Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 10/04/2023

To : ALLIANZ INSURANCE SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 05/04/2023

Vehicle No : SNH-5982-A

Make & Model : MAZDA 3 1.5 (A) SEDAN M-HYBRID CLASSIC

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	REAR BUMPER <i>de-</i>	985.00	✓
1	REAR BUMPER REINFORCEMENT ? X NN	480.00	
2	REAR BUMPER RETAINER X NN	119.00	
10	REAR BUMPER CLIPS <i>de-</i>	50.00	✓
2	REAR BUMPER REFLECTOR X NN	122.00	
2	REVERSE SENSOR ? X NN	1,080.00	
4	REVERSE SENSOR HOLDER ? X NN	230.00	
1	END PANEL ? X NN	576.00	
1	END PANEL TOP GARNISH X X NN	168.00	

Date : 10/04/2023

To : **ALLIANZ INSURANCE SINGAPORE PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 05/04/2023

Vehicle No : SNH-5982-A

Make & Model : MAZDA 3 1.5 (A) SEDAN M-HYBRID CLASSIC

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	RESTORE		
1	BOOT LID		
1	EMBLEM - MAZDA 3 <i>rec</i>	78.00	<i>p-1206</i>
1	EMBLEM - HYBRID <i>rec</i>	93.00	<i>supp- 75</i>
1	BOOT LID LOCK <i>X NN</i>	205.00	<i>1241</i>
1	REAR REMOTE SENSOR <i>X NN</i>	380.00	<i>208</i>
	Sub Total	4566.00	<i>992.80</i>
	Discount 20% On Parts	(913.20)	
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR	800.00	<i>300</i>
	TO RESPRAY AFFECTED AREAS	800.00	<i>400</i>
			<i>700</i>

*Supplementary Parts

REAR BUMPER TOW COVER RH \$35.00 ✓ MISSING

REAR NUMBE PLATE \$30.00 (SN) ✓ NEC

Date : 10/04/2023

To : ALLIANZ INSURANCE SINGAPORE PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 05/04/2023

Vehicle No : SNH-5982-A Make & Model : MAZDA 3 1.5 (A) SEDAN M-HYBRID CLASSIC

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	✓
	RUST PROOFING	80.00	X NN
	Sub Total	1710.00	
		5,362.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 992.80
L - 730.00
S/N - 30.00
T - 1752.80

Remarks:

3 days - P/P - Resy before paint

SUB TOTAL

GST 8.0 % 429.02

TOTAL 5,791.82

Surveyor's name:

Rasul - 4p 90010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 11/04/23 P 1450