

ASS. REC. BY:

REF:

AG/230036601ky

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s PART

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: V.B. / % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHB1222P Yr Regn: 09, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: MG 5 c.c. _____

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 177846 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LPJE 24037MG 051410

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size: F: Citi 205/60R16

R: Westlake

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 6/4/23 D.O.I. 10/4/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/9 @ 1819.59 Car

Date/Time, File Pass to?

: Prell. Report

: Final Report

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee:

Transportatn:

S-RS. SI

Fuel

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/04/2023

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SHB1222P
Case Reference Number	TAX/04/23/2016
Registration Date	16/9/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	CHAN KOK SENG
Type of Accident	Head to Rear
Accident Date and Time	6/4/2023 5:05 PM
Accident Reported Date and Time	8/4/2023 8:22 AM
Surveyor Required?	No
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118128
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	10/4/2023 11:32 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,200.00	\$0.00
Total Spray Cost	\$658.00	\$0.00
Total Spare Part Cost	\$2,670.53	\$0.00
Total Other Cost	\$1,000.00	\$0.00
TOTAL COST	\$5,528.53	\$0.00
ump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	2 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	10/04/2023 11:44 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part's prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/04/2023
User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR REAR PORTION	\$1,200.00 <i>4001</i>	
total Labour	\$1,200.00	

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY REAR BUMPER	\$428.00 <i>2301</i>	
O RESPRAY REAR PANEL	\$230.00 <i>nn X</i>	
total Spray Painting & Panel Beating	\$658.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00 <i>nn X</i>	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>201</i>	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00 <i>nn X</i>	
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00 <i>601</i>	
O REPLACE SUNDRY PARTS	\$100.00 <i>nn X</i>	
O CHECK & RESET SYSTEM FUNCTION	\$350.00 <i>nn X</i>	
ISOLATED OF (EV) (NET)	\$150.00 <i>nn X</i>	
total Other Costs	\$1,000.00	

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10395721-SEPP	PANEL ASM-RR END	1.00	\$708.66	10.00	\$637.79	Replace	<i>TL X</i>
		10369261-SPRP	FASCIA-RR BPR	1.00	\$758.48	10.00	\$682.63	Replace	<i>Bu ✓</i>
		10751490	FASCIA-RR BPR LWR	1.00	\$230.68	10.00	\$207.61	Replace	<i>ML ✓</i>
		10359003	FINISHER-RR BPR - RH	1.00	\$47.42	10.00	\$42.68	Replace	<i>CM ✓</i>
		10465727	BRACKET ASM-RR BPR FASCIA SI-RH	1.00	\$29.85	10.00	\$26.87	Replace	<i>SM X</i>
		10326371	BRACKET-RR BPR FASCIA SI MTG - RH	1.00	\$46.08	10.00	\$41.47	Replace	<i>SM X</i>
		10371790	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - RH	1.00	\$12.90	10.00	\$11.61	Replace	<i>ML X</i>
		90003417	SCRIVET-RR BPR FASCIA	2.00	\$0.84	10.00	\$1.51	Replace	<i>ML ✓</i>
		10327694	BAR ASM-RR BPR IMP	1.00	\$339.77	10.00	\$305.79	Replace	<i>R X</i>
		10587412	LAMP ASM-TAIL(LID SI) - RH	1.00	\$407.68	10.00	\$366.91	Replace	<i>(CPA) n/c X</i>
		10726677	LAMP ASM-RR FOG - RH	1.00	\$189.07	10.00	\$170.16	Replace	<i>CPA ✓</i>
		10376550-WSD	SENSOR-RR PARK DIST CONT	3.00	\$65.00	10.00	\$175.50	Replace	<i>ML X</i>
total					\$2,836.43		\$2,670.53		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									