

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ AIS 23003661/Up93**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD/TP WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBK 5281Rat Workshop m/s H.

of _____

Insured: XE 437EG

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \$72k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 17A \$18445Veh No: GBK 5281R Yr Regn: 27/08/20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CMMake: Toyota hiace c.c. 2982Colour: silver A/C: Insured / Std / NI / NASp. Reading: 85981 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT02P209990043Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 06/04/23 D.O.I. 10/4/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Dep 10k.</u>
<u>20/04/23</u>	<u>Home G14</u>
	<u>1/5 \$4500 inform Alen.</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$) S + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

2/5 # 45001
4 days
FASTTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: GBK 5281R

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1PC	REAR WINDSCREEN	17	\$1,288.10	X
1PC	TAILGATE	Boily 27	\$2,159.10	✓
1PC	TAILGATE REAR LOGO	111	\$85.10	✓
1PC	TAILGATE 'HIACE' STICKER	111	\$68.00	✓
1PC	TAILGATE 'TOYOTA' STICKER	111	\$82.00	X
1PC	TAILGATE WEATHERSTRIP	111	\$366.50	✓
1PC	TAILGATE INNER LOCK	11	\$398.50	X
1PC	TAILGATE INNER LOCK COVER	11	\$105.00	X
1PC	TAILGATE INNER TRIM	11	\$421.10	X
2PCS	TAILLAMPS @\$399.10	n/s n 0/5 sc	\$798.20	12C
2PCS	TAILLAMP LOWER GARNISHS @\$185.00	n/s n 0/5 7W	\$370.00	12C
2PCS	TAILLAMP HOUSING PANELS @\$499.00	n	\$998.00	X
1PC	REAR BUMPER	27	\$651.20	✓
1PC	REAR BUMPER INNER STEP BRACKET	11	\$245.50	X
4PCS	REAR BUMPER INNER LOWER BRACKETS @\$25.00	11	\$100.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$125.00	11	\$250.00	X
1PC	REAR END PANEL OUTER	27	\$945.10	✓
1PC	REAR END PANEL TOP PLATE	11	\$362.20	X
1PC	REAR EXHAUST	n	\$985.10	X
			\$10,678.70	

S.NETT

1PC	REAR WINDSCREEN SEALANT	111	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	111	\$50.00	40
1PC	TAILGATE '70Km/h STICKER	111	\$20.00	10
1SET	TAILGATE INNER ALUMINIUM PLATE	111	\$480.00	300
1SET	TAILGATE INNER ALUMINIUM RIVET	111	\$50.00	✓
1SET	REAR BUMPER CLIPS	111	\$50.00	✓
1SET	REAR BUMPER REVERSE SENSOR	111	\$280.00	X
1PC	REAR END PANEL SEALANT	111	\$50.00	✓

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX TAILGATE MECHANISM	\$100.00	60
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	X
TO SPRAY RUST PROOFING	\$100.00	60
TO RESET & REPROGRAMME SYSTEM	\$180.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$880.00	600
TO PUTTY & SPRAY PAINTING	\$1,200.00	650
TOTAL	\$14,548.70	

1-4728-1
252
3546.07
5417