					COMFORTDELGRO				
Our J	ob Ref	No :	305550810		ENGINEERING				
Date			13/04/23		ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156				
FINA	LIZATI	ON FORM			Fax: 6	546 8156			
То		and the second	LKK	harder's man	Fax:				
Attn	: Mr		NAZ	and the state of t					
Vehic	le Reg	No. : SHA4	323S	2		05.04.2023			
The s	urvey a	and estimates of	the repairs of the above-n	nentioned vehicle	are as follow				
1.	The re	epair job shall bill	to:A	ALLIANZ		SNH4311T			
2.	The fi	nalized amount s	shall be:		•				
	(a)	Spare Parts after	er List discount						
	(b)	Labour Charges	1						
	Total for Part-By-Part Repair Cost					\$0.00			
	(c.)	Lumpsum Repa Total for Lumps Final Lumpsum	um repair cost after Less:	20%		\$1,100.00 \$1,100.00			
3. 4.	Estimated normal period for repairs: 2 working days.  We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days								
5.	Thank	Thank you for your assistance.  We confirm the estimates and finalized amount							
	Signat	ure ;		Sig	nature:	$\mathcal{H}$			
Name : Ms. Loke YY				Na	NAZ LKK				
Tel : <u>62148355</u>				Da	Date : 21/4/2023				
	Fax	: 6546815	8						
For O	fficial	Use Only	The second secon	The same and the s	North Commence of the Commence				
	1	tem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks			
1. Re	Rental Rate P/Day			YES	Marine and the second of the s				
2. Loss of Income Paid				NO					
3. Survey Fees		ees		A Su		1			
4. LTA Search Fee			\$26.75 / \$2.00	A		TOTAL COST			
<ol><li>Medical Fees (on behalf of driver, if applicable)</li></ol>			and the second s						
6 Ov	errun	applicable)							
Rema	rks:			Parks of the second	Calcar discourse of the second	PROJECT CONTRACTOR			

## **COMFORT TRANSPORTATION PTE LTD**

## **REPAIR ESTIMATE**

Vehicle No.: SHA4323S

Make : HYUNDAI

Model : IONIQ

Date: 04/06/23

Insurance: ALLIANZ

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER COVER X R			\$459.40
10	REAR BUMPER CLIPS X NN			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER FOG LAMP X SVC			\$201.50
1	REAR BUMPER TOWING COVER			\$98.80
	SUB TOTAL			\$1,232.95
	LESS 25%			\$308.24
	DISCOUNTED TOTAL			\$924.71
	RENEW ADVERTISEMENT STICKER / N 5 C			\$250.00
	REAR NUMBER PLATE WITH TRIM COVER			\$55.00
	REAR BUMPER REVERSE SENSOR X 5V C			\$180.00
			NETT	\$485.00
	Labour Charge			
	PANEL BEATING			350 \$400.00
	SPRAY PAINTING CHARGE			250 \$300.00
	CHECK LIGHTING			~~ × \$60.00
ļ	REMOVE/REFIX REVERSE SENSOR			30 \$ <del>80.0</del> 0
	TOTAL LABOUR			\$840.00
	ESTIMATE TOTAL			\$2,249.71

8

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ CKK
61412013 1605
LIS
2 DAY)
AFTER FERMR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: