



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref:	CS/TP23003673/Uwy3m4
BLK 1 KAKI BUKIT AVE 6		Date:	08/05/2023
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE			
417883			
ON BEHALF OF YIN MINGBAO		Code:	TP149
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SKB 1474T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/04/2023
2. Vehicle Particulars & Condition			
Make & Model	BMW 318I (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAPF72040A794298	Colour	WHITE
Odometer	96934 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/04/2023	Inspection Date	11/04/2023
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	