

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23003678/TVY3Q2**Date:** 19/04/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZC00344
Claimant Vehicle No :	SHD4758E	Insured Vehicle No :	GBH1552B
Date of Loss:	04/04/2023	Nature of Claim:	TP
		Claim No:	M2302263

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4758E	Engine No:	2ZR2F76912
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU303089947
Reg. Date:	05/12/2019 (Man. Year: 2019)	Odometer:	437313 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,149.00	1,149.00	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	740.00	305.00	435.00	58.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,900.00	1,465.00	435.00	22.89
+ GST 8.00/8.00% (S\$)	152.00	117.20	34.80	22.89
Nett Amount (S\$)	2,052.00	1,582.20	469.80	22.89

INSPECTION

Date of Assignment:	10/04/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	11/04/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	1.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount:\$1,464.99

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD4758E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WING MIRROR LH	Cracked	1,390.10 FL	*1,390.10 FL
2	1		*WING MIRROR OUTER COVER LH	Missing	141.90 FL	*141.90 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					1,532.00	1,532.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					383.00	383.00
Total Parts (\$\$)					1,149.00	1,149.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	175.00
2	SPRAY PAINTING	New	300.00	100.00
3	CHECK WIRINGS	New	40.00	30.00
Gross Labour Cost (\$\$)			740.00	305.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >