



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts E	n Automol	bile
	ALLIANZ INSURAI	NCE SINGAPORE PTE LTD		Ref:	CS3/AIS23003703/Wnp3
	79 ROBINSON ROAD			Date:	11/04/2023
	#09-01 SINGAPOF	RE 068897		0 1	410
4		Daliau Dawiaulaua	/TUDD DADT	Code:	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBD 9513H	Veh. Inspected	<u> </u>	SMA 5242B
	Policy No.		Coverage (\$)		0.00
	Claim No.		Excess (\$)		0.00
	Assign From	SHANTI	Assign Date		07/04/2023
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	Year of Reg.			
	Chassis No. Colour				
	Odometer	Steering			
	Brakes	Modification			
	General				
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	General Information				
	Accident Date	05/04/2023	Inspection Da	te	11/04/2023
	Survey held at	QMO ENGINEERING	•		
	10 KAKI BUKIT ROAD 2, #03-18, FIRST EAST CENTRE, SINGAPORE 417868				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				