

Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-60, Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2004634144-01	Date of Loss:	06/04/2023
Vehicle Reg. No.:	SNB7235S	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WENG WEIMING	Contact No:	+6597336294
Driver:	WENG WEIMING		
Make/Model:	KIA CERATO, 1.6 SX (A)	Vehicle Reg. Date:	12/09/2018
Vehicle Colour:	WHITE		
Engine No:	G4FGJH703980	Chassis No:	KNAF3416MK5013621
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	1		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS

	Amount
Parts	4,986.30
Miscellaneous Items	1,720.00
Labour	2,400.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	9,106.30
- Excess (S\$)	600.00
(S\$)	8,506.30
+ GST 8.00% (S\$)	680.50
Nett Amount (S\$)	9,186.80

This claim is handled by: LAI JIA WEN RACHEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 10 Apr 2023)**Parts:** 143 KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Auto Bodyworks/SNB7235S/10/04/2023 12:09**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP LH	0.00	0.00	*1,250.00 F
2	1		*HEADLAMP RH	0.00	0.00	*1,250.00 F
3	1		*HEADLAMP LH BRACKET	0.00	0.00	*20.00 F
4	1		*FENDER FRT LH	0.00	0.00	*255.00 F
5	1		*FRT BUMPER	0.00	0.00	*380.00 F
6	1		*FRT BUMPER RETAINER LH	0.00	0.00	*20.00 F
7	1		*FRT FENDER LH INNER SHIELD COVER	0.00	0.00	*125.00 F
8	1		*FOGLAMP LH	0.00	0.00	*165.00 F
9	1		*FOGLAMP COVER LH	0.00	0.00	*18.00 F
10	1		*SPONGE	0.00	0.00	*105.00 F
11	1		*BONNET	0.00	0.00	*850.00 F
12	1		*SIGNAL LAMP LH	0.00	0.00	*95.00 F

F=Franchise part.

Sub Total (\$\$)	4,533.00
+ Margin on L,N Items 10.00% (\$\$)	453.30
Total Parts (\$\$)	4,986.30

Cheng Auto Bodyworks/SNB7235S/10/04/2023 12:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	BUMPER CLIPS	60.00
2	1	FENDER INNER CLIPS	60.00
3	1	RIM FRT LH	1,600.00
Sub Total (S\$)			1,720.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR	New	1,200.00
2	SPRAYPAINTING	New	1,000.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	100.00
4	CHECK & RE-ADJUST WHEEL ALIGNMENT	New	100.00
Gross Labour Cost (S\$)			2,400.00

Cheng Auto Bodyworks/SNB7235S/10/04/2023 12:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >