

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 12 Apr 2023

Preliminary Advice

Vehicle No	: SNB7235S	Accident Date	: 06/04/2023
Make	: KIA CERATO	Policy No.	: SP2004634144-01
Assignment Date	: 10/04/2023	Excess	: S\$600.00
Date of Inspection	: 11/04/2023	Est. Duration of Repair	: 4
Inspection At	: CHENG AUTO BODYWORKS (HQ) 5 SOON LEE STREET #01-60, PIONEER POINT SINGAPORE 627607		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,106.30
Revised Amount	:S\$	3,242.80
Check Items (Estimated)	:S\$	423.50
Total	:S\$	3,666.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	30,875.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,125.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO SECOND HAND PARTS AVAILABLE.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.