

**Cheng Auto Bodyworks** (Co.Reg.No:53315238X)

5 Soon Lee Street #01-60, Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

|                               |                        |                       |                   |
|-------------------------------|------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)        | Ref. No:              |                   |
| Policy No:                    | SP2004634144-01        | Date of Loss:         | 06/04/2023        |
| Vehicle Reg. No.:             | <b>SNB7235S</b>        | Driveable?            |                   |
| Driver Age/Info:              | / MALE                 | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                     | Third Party Involved? | YES               |
| Insured/Claimant:             | WENG WEIMING           | Contact No:           | +6597336294       |
| Driver:                       | WENG WEIMING           |                       |                   |
| Make/Model:                   | KIA CERATO, 1.6 SX (A) | Vehicle Reg. Date:    | 12/09/2018        |
| Vehicle Colour:               | WHITE                  |                       |                   |
| Engine No:                    | G4FGJH703980           | Chassis No:           | KNAF3416MK5013621 |
| Odometer:                     | 0 KM                   |                       |                   |
| Paint Type:                   |                        |                       |                   |
| Total Loss?                   | <b>NO</b>              |                       |                   |
| Est. Duration of Repair (day) | <b>1</b>               |                       |                   |

Present Location: **CHENG AUTO BODYWORKS (HQ)****COST OF CLAIMS**

|                                      | Amount          |
|--------------------------------------|-----------------|
| Parts                                | 4,986.30        |
| Miscellaneous Items                  | 1,720.00        |
| Labour                               | 2,400.00        |
| Paintwork Labour                     | 0.00            |
| Towing                               | 0.00            |
| <b>Calculated Gross Total (\$\$)</b> | <b>9,106.30</b> |
| <b>- Excess (\$\$)</b>               | <b>600.00</b>   |
| <b>(\$\$)</b>                        | <b>8,506.30</b> |
| <b>+ GST 8.00% (\$\$)</b>            | <b>680.50</b>   |
| <b>Nett Amount (\$\$)</b>            | <b>9,186.80</b> |

This claim is handled by: **LAI JIA WEN RACHEL**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

**REPAIR DETAILS****Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 10 Apr 2023)**Parts:** 143 **KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)****Labour:** Repairer's **(Price-denominated Standard List)****Print Code:** Cheng Auto Bodyworks/SNB7235S/10/04/2023 12:09**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

| No. | Qty | Part No. | Particulars                       | %Disc | %Depr | Amount                |
|-----|-----|----------|-----------------------------------|-------|-------|-----------------------|
| 1   | 1   |          | *HEADLAMP LH                      | 0.00  | 0.00  | *1,250.00 F BR        |
| 2   | 1   |          | *HEADLAMP RH <i>new</i>           | 0.00  | 0.00  | *1,250.00 F <i>BR</i> |
| 3   | 1   |          | *HEADLAMP LH BRACKET              | 0.00  | 0.00  | *20.00 F ?            |
| 4   | 1   |          | *FENDER FRT LH                    | 0.00  | 0.00  | *255.00 F BUC         |
| 5   | 1   |          | *FRT BUMPER                       | 0.00  | 0.00  | *380.00 F CUT         |
| 6   | 1   |          | *FRT BUMPER RETAINER LH           | 0.00  | 0.00  | *20.00 F NEC          |
| 7   | 1   |          | *FRT FENDER LH INNER SHIELD COVER | 0.00  | 0.00  | *125.00 F IN          |
| 8   | 1   |          | *FOGLAMP LH                       | 0.00  | 0.00  | *165.00 F ?           |
| 9   | 1   |          | *FOGLAMP COVER LH                 | 0.00  | 0.00  | *18.00 F CUT          |
| 10  | 1   |          | *SPONGE                           | 0.00  | 0.00  | *105.00 F ?           |
| 11  | 1   |          | *BONNET <i>new</i>                | 0.00  | 0.00  | *850.00 F <i>BR</i>   |
| 12  | 1   |          | *SIGNAL LAMP LH                   | 0.00  | 0.00  | *95.00 F ?            |

F=Franchise part.

|                                            |                 |
|--------------------------------------------|-----------------|
| <b>Sub Total (\$\$)</b>                    | <b>4,533.00</b> |
| <b>+ Margin on L,N Items 10.00% (\$\$)</b> | <b>453.30</b>   |
| <b>Total Parts (\$\$)</b>                  | <b>4,986.30</b> |

Cheng Auto Bodyworks/SNB7235S/10/04/2023 12:09. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars        | Amount       |
|----------------------------|-----|--------------------|--------------|
| <u>Miscellaneous Items</u> |     |                    |              |
| 1                          | 1   | BUMPER CLIPS       | 30 60.00 NEC |
| 2                          | 1   | FENDER INNER CLIPS | 30 60.00 NEC |
| 3                          | 1   | RIM FRT LH         | 1,600.00     |
| Sub Total (S\$)            |     |                    | 1,720.00     |

## Estimates on Labour

| No                      | Particulars                                                                                                                                | Lab.Type | Amount         |
|-------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|----------|----------------|
| <u>Labour Items</u>     |                                                                                                                                            |          |                |
| 1                       | LABOUR                                                                                                                                     | New      | 500 1,200.00 ✓ |
| 2                       | SPRAYPAINTING                                                                                                                              | New      | 400 1,000.00 ✓ |
| 3                       | DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING | New      | 30 100.00 ✓    |
| 4                       | CHECK & RE-ADJUST WHEEL ALIGNMENT                                                                                                          | New      | 100.00 ✓       |
| Gross Labour Cost (S\$) |                                                                                                                                            |          | 2,400.00       |

Cheng Auto Bodyworks/SNB7235S/10/04/2023 12:09. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- NOT AUTHORISE
  - EXCESS \$600
  - P/P OR L/S REPAIR?
  - SURVEY BY EDWARD TEL 62563561
  - RESURVEY BEFORE PAINT FOR P/P REPAIR.
- 4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: