

(08/11/13) wef

ASS. REC. BY Marcus

REF:

CS/C7/23003708/4923

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNA5707R

at Workshop m/s hookway

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 105k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 1.3 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

407c
Vehicle: IN / OUT

Date: _____ Person Contacted: 271145776

Veh No: SNA5707R Yr Regn: 29/06/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: mgtda 3 M-Hybrid.c.c 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp.Reading: 26099 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BP2SA*AM1107819

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 06/04/23

D.O.I. 22/5/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

nil s.f.t.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 13k.

24/5/23 inbound Anyse 2/2 & 550 and 2 days (Red 330, 38%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 2

Resurvey No. of Trip: 1

1) 24/5/23 Final

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : MEK-TP

Lump Sum / I.B.I. (\$) 550

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 98235236
ONG CHYE HUE
BLK 94D BEDOK NORTH AVENUE 4
#13-1421
SINGAPORE 460094
TEL : FAX :
PH : 98235236
ATTN :

ESTIMATE BILL

Number : EB00006262
Date : 10/04/2023
Case No : AD00013789
Vehicle No : SNA5707R
Chassis : JM6BP2SAAM1107819
Year of Mfr : 2021
Policy No : 5127823906
Model : MAZDA 3 4-DOOR
SEDAN 1.5L SP.6EAT

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT BUMPER - REPAIR 2 X	1.0			
2	FRONT FENDER LH - REPAIR 2 X	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					0.00
3	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	400.00	0	150 400.00
4	SPRAY PAINT ON THE AFFECTED AREAS	1.0	400.00	0	400.00
5	ANTI-RUST COATING	1.0	80.00	0	11 80.00
Labour 1 Sub Total					880.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : NINE HUNDRED FIFTY AND CENTS FORTY ONLY			Less Excess		0.00
			SUBTOTAL		880.00
			GST 8.00%		70.40
			TOTAL		950.40

Date of accident : 06/04/2023 10:45 AM. Place : OPENSOURCE CARPARK LOT 320 & LOT 321

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE