



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

NO. : 43156

DATE : 10/04/2023
CLAIM NO. : 12150
POLICY NO. : MC/01011811
FROM : RAYMOND

VEHICLE NO. : FBS6900P
MAKE/MODEL : VESPA / GTS 150 ABS

Not Allowed

P17 \$
the plate RPA 14
3 days
11/4/23

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AIR CLEANER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$163.00	163.00
2	BEADING WINDSHIELD RH P/N: 30066 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	71.00
3	LABOUR P/N: 06766 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$86.00	430.00
4	Spray paint rear box to matte grey	Spray	1.00	\$220.00	220.00
5	Spray Paint Rear LH Cover to white	Spray	1.00	\$90.00	90.00
SUB TOTAL					\$974.00
GST @ 8 %					\$77.92
GRAND TOTAL (SGD)					\$1,051.92

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



RAYMOND

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Acknowledge & Accepted By

*43156 *

bizSAFE₃

