



SINGAPORE CIVIL DEFENCE FORCE

## FIRE REPORT

<b>1. GENERAL INFORMATION</b>		
INCIDENT NO.: /20230213/1187	LOCATION OF FIRE:  Along East Coast Parkway (Towards Changi Airport) Near Lamp Post 1611 Singapore	
FIRE REPORTED ON: 13 February 2023		
TIME OF CALL: 19:13:26 hrs		
STATION COVERAGE: Paya Lebar Fire Station		
<b>2. INCIDENT INFORMATION</b>		
FIRE INVOLVED: The engine compartment of a Volvo tipper truck (XD9541R).		
METHOD OF EXTINGUISHMENT: By SCDF crew using a hose line jet from a fire appliance.		
PROBABLE CAUSE OF FIRE: Accidental (Overheating / Electrical origin at the engine compartment of the tipper truck)		
DAMAGE OBSERVED*: As a result of the fire, the engine compartment of the tipper truck was damaged. The passenger cabin and other parts of the tipper truck sustained heat, smoke and water damage. The railings and vegetation in the area sustained heat and smoke damage. SCDF crew forced opened the driver's door for firefighting.		
<b>3. FATALITY/INJURY INFORMATION</b>		
NAME	NRIC/FIN	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL
<b>REPORT ISSUED BY:</b> FONG CHUN HERN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE		

*\*This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.*

*This is a computer generated report. No signature is required.*