



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01  
SINGAPORE 068897

*Not Authorised  
Recovery B4 paint*

## ESTIMATE

NO : QUOT202304-000023(00)

DATE : 11/04/2023

POLICY NO : SP2003907937

VEH REG NO : SNG7311D

MAKE/MODEL : MERCEDES BENZ E200 SEDAN  
AVG (R18 LED)

CHASSIS NO : WDD2130802A672697

ENGINE NO : 26492080001492

REG. DATE : 2019

ATTN : MOTOR CLAIMS DEPT

TEL :

FAX : *Ex TBA*

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 23/03/2023

*12/4/23 4 days*

### Estimate Repair Cost to Vehicle No : SNG7311D

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>PARTS</b>			
1 Front door - RH	1	1,450.00	1,450.00 ✓
2 Front door weatherstrip - RH	1	238.00	238.00 ✓
3 Front door trimboard rivets - RH	20	<i>60SN</i> 12.00	<i>240.00</i> ✓
4 Front door hinges - RH	2	125.00	250.00 ✓
5 Front door lower seal	1	48.00	48.00 ✓
6 Front fender - RH	1	720.00	720.00 ✓
7 Front fender vertical garnish - RH	1	38.00	38.00 ✓
			2,984.00
		Add 10%	298.40
			3,282.40
<b>LABOUR</b>			
8 To transfer RH front damaged door interior mechanism and glass to new door	1	150.00	150.00 ✓
9 To check and rectify wiring system	1	80.00	80.00 ✓
10 To panel beat & straighten RH front door pillar, RH front fender inner panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 ✓
11 To putty and spray paint on affected areas <i>Side skirt</i>	1	1,000.00	1,000.00 ✓
			2,230.00
		TOTAL	S\$ 5,512.40
		ADD GST @ 8%	440.99
		GRAND TOTAL	S\$ 5,953.39

*10% \$ 3,282.40  
\$ 3,744.00  
\$ 374.40  
\$ 3,018.40*

*60SN  
601  
201  
400  
4401  
1030*

SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED FIFTY-THREE AND CENTS THIRTY-NINE ONLY

FOR TONG LUCK AUTO PTE LTD  
  
AUTHORISED SIGNATURE



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD  
79, ROBINSON ROAD #09-01  
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT  
TEL : FAX :

YOUR REF NO :  
CLAIM TYPE : OWN DAMAGE  
ACCIDENT DATE : 23/03/2023

## ESTIMATE

NO : QUOT202304-000023(00)  
DATE : 28/04/2023  
POLICY NO : SP2003907937  
VEH REG NO : SNG7311D  
MAKE/MODEL : MERCEDES BENZ E200 SEDAN  
AVG (R18 LED)  
CHASSIS NO : WDD2130802A672697  
ENGINE NO : 26492080001492  
REG. DATE : 2019

### Estimate Repair Cost to Vehicle No : SNG7311D

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>SUPPLEMENTARY PARTS</b>			
1 Side skirt - RH	1	dd 520.00	520.00
2 Side skirt clips - RH	16	nec 8.00	128.00
			648.00
		Add 10%	64.80
			712.80
		TOTAL	<b>S\$ 712.80</b>
		ADD GST @ 8%	57.02
		GRAND TOTAL	<b>S\$ 769.82</b>

SINGAPORE DOLLAR SEVEN HUNDRED SIXTY-NINE AND CENTS EIGHTY-TWO ONLY

Parts: \$ 3,018.40  
 SN : 60.00  
 Labour : 1,030.00  
 Supp : 648.00  
 -----  
 \$ 4,756.40  
 XS 700.00  
 -----  
 \$ 4,056.40  
 8% 324.51  
 -----  
 \$ 4,380.91

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE