

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 12 Apr 2023

Preliminary Advice

Vehicle No	: SNG7311D	Accident Date	: 23/03/2023
Make	: MERCEDES-BENZ E200	Policy No.	: SP2003907937
Assignment Date	: 11/04/2023	Excess	: S\$0.00
Date of Inspection	: 12/04/2023	Est. Duration of Repair	: 4
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,512.40
Revised Amount	:S\$	4,202.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,202.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	186,000.00
COE / PARF Rebate	:S\$	85,300.00
Salvage Value	:S\$	
Margin for Repair	:S\$	100,700.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :the vehicle repair *on part by parts basis.due to no second hand parts available.*
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.