



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD
79, ROBINSON ROAD #09-01
SINGAPORE 068897

TEL : 67143369 FAX :
ATTN: MOTOR CLAIMS DEPT

YOUR REF NO
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 28/03/2023

TAX INVOICE

NO : AR202305-0026
CLAIM NO : QUOT202304-000025(01)
DATE : 17/05/2023
POLICY NO : SP2003907937
VEH REG : SMM2032Y
MAKE/MODEL : MERCEDES BENZ S320L
(R19 LED)
CHASSIS NO : WDD2221622A464637
ENGINE NO : 27682431002517
REG. DATE : 2019

Final Repair Cost to Vehicle No : SMM2032Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Rear door - LH	1	1,950.00	1,950.00
2 Rear door weatherstrip - LH	1	238.00	238.00
3 Rear door outer handle - LH	1	380.00	380.00
4 Rear door lower chrome - LH	1	148.00	148.00
5 Rear sport rim - LH	1	950.00	950.00
			3,666.00
		Add 10%	366.60
			4,032.60
SPECIAL NET			
6 Rear door trimboard rivets - LH (set)	1	60.00	60.00
7 Rear windscreen sealant	1	40.00	40.00
			100.00
LABOUR			
9 To putty and spray paint on affected areas	1	660.00	660.00
10 To computerise check wheel alignment	1	60.00	60.00
11 To remove and refit rear cushion seat, speaker board and all inner garnishes and trimboard to facilitates the repair	1	120.00	120.00
12 To transfer LH rear damaged door interior mechanism and glass to new door	1	60.00	60.00
13 To check and rectify wiring system	1	20.00	20.00
14 To panel beat and straighten LH rear chassis frame, LH rear fender inner panel, LH rear wheel arch panel, to cut and weld LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	600.00	600.00
			1,520.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

TEL : 67143369

FAX :

ATTN: MOTOR CLAIMS DEPT

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 28/03/2023

NO : AR202305-0026

CLAIM NO : QUOT202304-000025(01)

DATE : 17/05/2023

POLICY NO : SP2003907937

VEH REG : SMM2032Y

MAKE/MODEL : MERCEDES BENZ S320L
(R19 LED)

CHASIS NO : WDD2221622A464637

ENGINE NO : 27682431002517

REG. DATE : 2019

Final Repair Cost to Vehicle No : SMM2032Y

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
		AMOUNT:	S\$ 5,652.60
		LESS EXCESS:	S\$ 1,000.00
		TOTAL:	S\$ 4,652.60
		ADD GST @ 8%:	S\$ 372.21
		GRAND TOTAL:	<u>S\$ 5,024.81</u>

SINGAPORE DOLLARS FIVE THOUSAND TWENTY-FOUR AND CENTS EIGHTY-ONE ONLY

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE