

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003737/RQP3E2**Date:** 01/08/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00130472202

**Claimant Vehicle
No :** SLV1467Y**Insured Vehicle
No :** GBH9339Z

Date of Loss: 25/03/2023

Nature of Claim: TP

Claim
No: SNM23D202282/C02/LEWLCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLV1467Y**

Make & Model: TOYOTA SIENTA HYBRID, 1.5 X CVT (A)

Engine No: 1NZ8292693

Reg. Date: 22/12/2017 (Man. Year: 2017)

Chassis No: NHP1707100324

Colour: Grey

Odometer: 338877 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,133.07	970.57	1,162.50	54.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	550.00	450.00	45.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,133.07	1,520.57	1,612.50	51.47
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	3,133.07	1,200.00	1,933.07	61.70
+ GST 8.00/8.00% (S\$)	250.65	96.00	154.65	61.70
Nett Amount (S\$)	3,383.72	1,296.00	2,087.72	61.70

INSPECTION

Date of Assignment: 11/04/2023

Date Inspected: 12/04/2023

Inspected At: 48 Toh Guan Road East, #01-141
Repairer: Af & Cars Pte Ltd (HQ)

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2023)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV1467Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Bent	1,294.10 FL	*1,294.10 FL
2	1		*REAR DOOR GLASS LH	Not Necessary	240.00 FL	*- FL
3	1		*REAR DOOR POWER SLIDE LH	Not Necessary	900.00 FL	*- FL
4	1		*REAR DOOR HINGE LH	Not Necessary	90.00 FL	*- FL
5	1		*REAR DOOR ROLLER UPPER LH	Not Necessary	180.00 FL	*- FL
6	1		*REAR DOOR ROLLER LOWER LH	Not Necessary	140.00 FL	*- FL
					Sub Total (\$\$)	2,844.10 1,294.10
					- List Item Discount on L Items 25.00/25.00% (\$\$)	711.03 323.53
					Total Parts (\$\$)	2,133.07 970.57

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY, PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	600.00	300.00
2	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE DAMAGED BODYPARTS, REPAIR, ALIGN BODY STRUCTURE & DAMAGED AND WHERE CONSISTENT TO THE ACCIDENT	New	400.00	250.00
Gross Labour Cost (\$\$)			1,000.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >