

(08/11/13) wef

ASS REC BY: [Signature]

REF:

CS/CT123003737/Rqp3

731M

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TF/WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLV 14674at Workshop m/s AF & CARS P/Lof 48, POA Gum Rd East #01-141Insured: CTI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

41LIN

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 70K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLV 14674 Yr Regn: 2017 / DECType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA SIENNA HYBRID 1.5G c.c. 1496Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 338877 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NHP 170 7100 324Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKE or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 25/03/23 D.O.I. 12/04/23Survey held at AF & CARSDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 46K

Prelim finalised vs \$1200, 2 days. Cred \$1939.08, 67%

Date/Time, File Pass to?

1) 3/7/2019

Date/Time, File Return to?

2) _____

☐ : Prelim. Report☐ : Final ReportDays Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: MEP-TPLump Sum / I.B.f. (\$) 1200

AF & CARS PTE LTD

NO.48 TOH GUAN ROAD EAST

#01-141 ENTERPRISE HUB

SINGAPORE 608586

M: 86118181

CLT LEASING PTE LTD

Estimate

Code: AF-000116
Date: 11-Apr-23
Vehicle No. SLV1467Y
Model: TOYOTA SIENTA
CHASSIS#: NHP1707100324

NO.	Particular	Quantity	Unit Price	Amount
LIST PRICE PARTS				
1	REAR DOOR LH <i>51</i>	1	\$1,294.10	\$1,294.10
2	REAR DOOR GLASS LH <i>XN</i>	1	\$240.00	\$240.00
3	REAR DOOR POWER SLIDE LH <i>XN</i>	1	\$900.00	\$900.00
4	REAR DOOR HINGE LH <i>XN</i>	1	\$90.00	\$90.00
5	REAR DOOR ROLLER UPPER LH <i>XN</i>	1	\$180.00	\$180.00
6	REAR DOOR ROLLER LOWER LH <i>XN</i>	1	\$140.00	\$140.00
SUB-TOTAL BEFORE DISCOUNT				\$2,844.10
PERCENTAGE DISCOUNT 25%				\$711.03
Sub-total 1				\$2,133.08
LABOUR				
1	To respray, painting on the change bodyparts, repair portion and where consistent to the accident	1	\$600.00	\$600.00 <i>300</i>
2	To provide labour, workmanship to change damaged bodyparts, repair, align body structure & damaged and where consistent to the accident	1	\$400.00	\$400.00 <i>250</i>
Sub-total 2				\$1,000.00
Total for Parts & Labour				\$3,133.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

970.57
550.00
1520.57
20%
1216.45
L/S - \$1,200

2 days
12/04/23
Reg after repair