

ASS. REC. BY:

REF:

LPC/23-003741/Kcp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

LHM/c

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMH 14557

Yr Regn:

01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Attrage

c.c.

1193

Colour

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

164377

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MMBSTA13AJH - 004472

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Tourador

Front

Rear

R/Bal.

8 mm

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

7/4/23

D.O.I.

21/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/11 2 4807.86 Conhr

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

P. m/s

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0031800
Norman Siok Khoon Lay

Page 1 of 2
Your ref. TP-GBJ 8955R Lonpac
Job No. 73494
Our ref 23.04.08
Payment
Date 11/4/2023

Attn

Vehicle No SMH 1455T
Vehicle Model : Mitsubishi Attrage
Accident on ... 7/4/2023

*NOT Withhold
Resurvey B& paint
@ 4807.86 6 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear boot lid	820.00	10.00	<i>R</i> 738.00
1.00	Pc	Rear boot lid chrome moulding	346.00	10.00	<i>CM</i> 311.40
1.00	Pc	Rear boot lid lock	224.00	10.00	<i>R</i> 201.60
1.00	Pc	Rear Attrage emblem	28.00	10.00	<i>RC</i> 25.20
1.00	Pc	Rear logo emblem	86.00	10.00	<i>RC</i> 77.40
1.00	Pc	Rear bumper <i>765</i>	<i>CM</i> 1,268.00	10.00	1,141.20
4.00	Pcs	Rear bumper clips	5.00	10.00	<i>RC</i> 18.00
1.00	Pc	Rear bumper side retainer RH	43.00	10.00	<i>DI</i> 38.70
1.00	Pc	Rear taillamp RH <i>335.40</i>	661.00	10.00	<i>CM</i> 594.90
1.00	Pc	Rear end panel	440.00	10.00	<i>R</i> 396.00
1.00	Pc	Rear end panel cover	<i>my DI</i> 68.00	10.00	61.20
1.00	Pc	Rear spare tyre top cover	<i>R</i> 1,201.00	10.00	1,080.90
Labour & Misc:					
1.00		To transfer rear parking sensor	60.00		60.00
1.00		To straighten rear body including cutting	900.00		<i>800</i> 900.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from students. (temporarily)

Acknowledged by Repairer

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0031800
Norman Siok Khoon Lay

Page: 2 of 2
Your ref.: TP-GBJ 8955R Lonpac
Job No.: 73494
Our ref: 23.04.08
Payment
Date: 11/4/2023

Attn

Vehicle No: SMH 1455T
Vehicle Model : Mitsubishi Attrage
Accident on ...: 7/4/2023

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		and welding, to knock dents on rear fender RH and renew of parts			
1.00		To spray paint (Pearl white/include blend to roof panel RH, rear fender LH)	1,600.00		1,600.00

1100h

Sub-Total 7,244.50
GST 8.00% 579.56
Total S\$ 7,824.06

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."