

Date: 11/04/2023  
 Vehicle No: SMZ5558J  
 Model: TESLA MODEL Y RWD  
 Chassis: LRWYHCFXNC574906-2022  
 Reg. Year: 2022

Third Party Insurer: ALLIANZ  
 Third Party Veh No: SJM4786C  
 Date of Accident: 09/04/2023  
 Estimator: TING AN  
 Surveyor:

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER LOWER LIP	1		CM \$542.06
2	REAR BUMPER REINFORCEMENT	1		\$299.07
3	REAR BUMPER TOW COVER	1		2.1 \$20.56
4	REAR BUMPER REFLECTOR RH	1		\$40.19
5	REAR BUMPER	1		REPAIR
SUB TOTAL				\$901.88
LESS 10%				-\$90.19
PARTS TOTAL				\$811.69

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$300.00

150

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC.

\$300.00

7

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00

15

LABOUR TOTAL \$720.00

TING AN

TOTAL

\$1,531.69

Not Notation  
 1 day

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

### Head office

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554600  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1903

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

