

# ADVANCE AUTO GARAGE

TP Allianz  
Ezyra

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE  
SINGAPORE 417868  
TEL: 90079247

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Excess material (item/s) must be resurveyed and subject to final approval from Insurance Company

acknowledged by Repairer  
Signature:  
Date:

## VEHICLE DETAILS

VEHICLE NO : GBL8304J 2022 MAY  
VEHICLE MODEL : TOYOTA HIACE  
CHASSIS NO : TRH2000351556

## CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Delnd</i>	1	\$ 686.50	\$ 686.50
2	REAR BUMPER SIDE HOLDER <i>Delnd</i>	1	\$ 44.60	\$ 44.60
3	TAILLAMP <i>Crack</i>	1	\$ 367.90	\$ 367.90
4	TAILLAMP LOWER APRON <i>Delnd</i>	1	\$ 109.20	\$ 109.20
5	REAR FENDER <i>Dented</i>	1	\$ 1,840.40	\$ 1,840.40
6	REAR FENDER AIR VENT <i>Delnd</i>	1	\$ 60.90	\$ 60.90
7	REAR FENER INNER PANEL <i>Delnd</i>	1	\$ 1,250.90	\$ 1,250.90
8	REAR FENDER INNER TRIM BOARD <i>Delnd</i>	1	\$ 185.20	\$ 185.20

TOTAL PRICE: \$ 4,545.60  
LESS 25% \$ 1,136.40  
SUB TOTAL PRICE: \$ 3,409.20

*3109.50*  
*2332.12*

## SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>Free</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR FENDER SEALANT <i>Free</i>	1	\$ 60.00	\$ 60.00
3	REAR FENDER GLASS SEALANT <i>Free</i>	1	\$ 60.00	\$ 60.00
4	REAR FENER INNER TRIM BOARD CLIPS <i>Free</i>	1 SET	\$ 30.00	\$ 30.00

TOTAL : \$ 180.00

*150*

## LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ <del>1,200.00</del>	<i>600</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ <del>800.00</del>	<i>550</i>	
3	WIRING CHECK	\$ <del>50.00</del>	<i>30</i>	
4	TO APPLY TUFF COAT	\$ <del>150.00</del>	<i>60</i>	
5	TO REMOVE REVERSE SENSOR	\$ <del>100.00</del>	<i>50</i>	
6	TO REMOVE UPHOLSTRY	\$ <del>150.00</del>	<i>60</i>	
7	TO REMOVE REAR FENDER GLASS	\$ <del>120.00</del>	<i>60</i>	

TOTAL: \$ 2,570.00

*1410*

## ESTIMATE REPORT

TOTAL PARTS COST: \$ 3,589.20  
TOTAL LABOUR COST: \$ 2,570.00  
TOTAL REPAIR COST: \$ 6,159.20

*total 3892.12*  
*4/s 3.11k*  
*OSDys*

*3100*  
*5 days*