

ASS. REC. BY: Taufik

REF:

INC

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SM74126 Yr Regn: 2019, Dec
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius Hybrid c.c. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 472737 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKB3ZF4103089557
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: 27

N/S	O/S
	<input checked="" type="checkbox"/>

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: WP
 Vehicle: IN / OUT away

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 11/4/23
 Survey held at Comfort Logam
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Near o/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?

Days Of Repair: _____
 Resurvey No. of Trip: _____

2) _____
 Report Format: _____
 Lump Sum / I.B.L. (%) _____

Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee:	_____
Transportation:	_____
\$ + RS. SI	_____
Photos	_____
Others	_____
TOTAL	_____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH7412G

08.04.2023

MAKE Reg.08.04.2023

CHIANG/ INCOME

MODEL TOYOTA PRIUS G4a

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER		de ✓ \$551.89
1	REAR BUMPER REINFORCEMENT		X \$378.32
1	REAR BUMPER SIDE RETAINER RH		? \$112.70
1	REAR BUMPER LOWER COVER		at ✓ \$654.96
10	REAR BUMPER CLIPS	\$2.20	nee ✓ \$22.00
1	REAR BUMPER TOW COVER		cut ✓ \$82.70
1	REAR BUMPER REFLECTOR RH		? \$55.00
	SUB TOTAL		\$1,857.57
	25.00%		\$464.39
	DISCOUNTED TOTAL		\$1,393.18
1	REAR BUMPER MAT		nee ✓ \$50.00
1	REAR REVERSE SENSOR		X \$135.70
			\$185.70
	Labour Charge		
	Panel Beating	350	\$750.00
	Spray Painting Charge	250	\$600.00
	Tuff Kote	X	\$60.00
	Check Lighting	X	\$60.00
	TOTAL LABOUR		\$1,470.00
	ESTIMATE TOTAL		\$3,048.87

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjong 97495749
 WP' 11/4/23 @ 4pm
 ~ 2 days
 L/S rising after repair
 Tanjun C/Mantou

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5892581

JC NO305550926


CUSTOMER /MS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO.: SH 7412G	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL: PRIUS HYBRID(G4A11.04.2023 08:00	DATE/TIME IN
	YR OF MANU: 05.12.2019	TARGET DATE
	CHASSIS CODE: JTDKB3FU103089557	COMPLETION DATE/TIME:
	COUNT CARD NO.	

JOB DESCRIPTION

Accident Date: 08.04.2023

NATURE: 3P 08.04.2023

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 7412G CHIANG

Vehicle No.: SH 7412G

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard