

ASS. REC. BY: Taufikh

REF:

INC NS/INC23003760/Tny3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. MT/1217812-002  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SM74126 Yr Regn: 2019, Dec  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Prius MyPrio c.c. 1798  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 472737 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTDKB3ZF4103089557  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195/65R15  
 R: 27  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Westlake  
 Front R/Bal. 6 mm Rear R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 11/4/23  
 Survey held at Comfort Lodge  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Near o/s  
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S
	<input checked="" type="checkbox"/>

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: WP  
 Vehicle: IN / OUT away

Date / Time	Action / Instruction
	Taufikh confirmed final fig \$1300 and 2 days (red, \$1748.87, 57%)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) 03/05/23  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Format : \_\_\_\_\_  
 Lump Sum / I.B.H. (%) \_\_\_\_\_

Days Of Repair: 2  
 Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : Weekend (\$) \_\_\_\_\_

Survey Fee:	
Transportation:	
\$ + RS. SI	
Photos	
Others	
TOTAL	

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO SH7412G

08.04.2023

MAKE Reg.08.04.2023

CHIANG/ INCOME

MODEL TOYOTA PRIUS G4a

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER		de ✓ \$551.89
1	REAR BUMPER REINFORCEMENT		X \$378.32
1	REAR BUMPER SIDE RETAINER RH		? \$112.70
1	REAR BUMPER LOWER COVER		at ✓ \$654.96
10	REAR BUMPER CLIPS	\$2.20	nee ✓ \$22.00
1	REAR BUMPER TOW COVER		cut ✓ \$82.70
1	REAR BUMPER REFLECTOR RH		? \$55.00
	<b>SUB TOTAL</b>		<b>\$1,857.57</b>
	25.00%		\$464.39
	<b>DISCOUNTED TOTAL</b>		<b>\$1,393.18</b>
1	REAR BUMPER MAT		nee ✓ \$50.00
1	REAR REVERSE SENSOR		X \$135.70
			<b>\$185.70</b>
	<b>Labour Charge</b>		
	Panel Beating	350	\$750.00
	Spray Painting Charge	250	\$600.00
	Tuff Kote	X	\$60.00
	Check Lighting	X	\$60.00
	<b>TOTAL LABOUR</b>		<b>\$1,470.00</b>
	<b>ESTIMATE TOTAL</b>		<b>\$3,048.87</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjong 97495749  
 WP' 11/4/23 @ 4pm  
 ~ 2 days  
 L/S rising after repair  
 Tanjoh C/Mantoum

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Team: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order: 5892581

JC NO305550926


CUSTOMER /MS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO: SH 7412G	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL: PRIUS HYBRID(G4A11.04.2023 08:00	DATE/TIME IN
	YR OF MANU: 05.12.2019	TARGET DATE
	CHASSIS CODE: JTDKB3FU103089557	COMPLETION DATE/TIME:
	COUNT CARD NO.	

JOB DESCRIPTION

Accident Date: 08.04.2023

NATURE: 3P 08.04.2023

3/NO                      LABOR CODE                      DESCRIPTION



CHECKED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
SERVICE ADVISOR

\_\_\_\_\_  
CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 7412G                      CHIANG

Vehicle No.: SH 7412G

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard