

ASS

MFC RTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD3244C

11.04.2023

MAKE :

MODEL HYU- I40

CHIANG/ INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$428.40
2	REAR BUMPER REFLECTOR LH/RH		\$32.00	\$64.00
1	REAR BUMPER UNDER COVER			\$228.00
			1356	\$1,919.60
	20.00% DISCOUNTED TOTAL		1084.80	\$383.92
				\$1,535.68
1	BUMPER ADVERTISEMENT		50	\$50.00
				\$50.00
	Labour Charge			
	Panel Beating			\$480.00
	Spray Painting Charge			\$300.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote		560	\$60.00
	TOTAL LABOUR		1694.80	\$900.00
	ESTIMATE TOTAL		6813.50	\$2,485.65
			2 days #	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tan Jia 97445749
 'wp' 11/4/23 @ 430pm
 1/5 Resurvey after repair
 2 days
 Tan Jia @ 11/4/23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: