



## REPAIR ESTIMATE\*

VEHICLE NO SHD3244C

11.04.2023

MAKE :

MODEL HYU- I40

CHIANG/ INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$428.40
2	REAR BUMPER REFLECTOR LH/RH		\$32.00	\$64.00
1	REAR BUMPER UNDER COVER			\$228.00
				<b>\$1,919.60</b>
				<b>\$383.92</b>
				<b>\$1,535.68</b>
1	BUMPER ADVERTISEMENT			\$50.00
				<b>\$50.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$480.00
	Spray Painting Charge			\$300.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote			\$60.00
				<b>\$900.00</b>
				<b>\$2,485.65</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tan Jia 97445749  
 'wp' 11/4/23 @ 430pm  
 L/S Resurvey after repair  
 2 days  
 Tan Jia @ 11/4/23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

Team: ARC Repair TP(CLSO)1	JOB CARD Sales Order: 5892674	JC NO305550948
Customer: COMFORT TRANSPORTATION PTE LTD MS 7010045 Customer No. 383 SIN MING DRIVE Address Singapore SINGAPORE 575717 (R) 65508755 (O) (P)	REGN NO: SHD3244C MAKE: HYUNDAI MODEL: I-40 YR OF MANU: 08.07.2016 CHASSIS CODE: KMHLB41UMGU091865	MILEAGE FUEL E.....1/2.....F DATE/TIME IN: 11.04.2023 12:50 TARGET DATE COMPLETION DATE/TIME:
COUNT CARD NO.		

Accident Date: 11.04.2023  
Nature: 3P 11.04.2023

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD3244C CHIANG

Vehicle No.: SHD3244C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard