



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ALLIANZ
Policy No:	SP2002871503	Date of Loss:	03/04/2023
Vehicle Reg. No.:	SMW6356J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KOON PENG HWEE		
Driver:	KOON PENG HWEE		

Make/Model:	NISSAN SYLPHY, 1.6 CVT (A)	Vehicle Reg. Date:	30/11/2020
Vehicle Colour:	SILVER		
Engine No:	HR16954275C	Chassis No:	MNTBBAB17Z0037574
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	0

Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS

	Amount
Parts	874.50
Miscellaneous Items	0.00
Labour	1,560.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,434.50
+ GST 8.00% (S\$)	194.76
Nett Amount (S\$)	2,629.26

This claim is handled by: **SHARON CHIONG BENG CHOON**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 11 Apr 2023)**Parts:** 143 **NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)****Labour:** Repairer's **(Price-denominated Standard List)****Print Code:** Cheng Hoe Motor Pte Ltd/SMW6356J/11/04/2023 15:58**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR RH DOOR	0.00	0.00	*600.00 F _{BLU}
2	1		*1 PC REAR RH DOOR OUTER HANDLE	0.00	0.00	*100.00 F _{BLU} ?
3	1		*1 SET REAR LH DOOR FRAME STICKER	0.00	0.00	*60.00 F _{BLU} NE
4	1		*1 PC LH FENDER STICKER	0.00	0.00	*35.00 F _{BLU} NE
F=Franchise part.						
Sub Total (\$)						795.00
+ Margin on L,N Items 10.00% (\$)						79.50
Total Parts (\$)						874.50

Cheng Hoe Motor Pte Ltd/SMW6356J/11/04/2023 15:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & REFIX REAR LH DOOR, TRANSFER LOCK ASSY, TRIM BOARD, RUBBER. TO KNOCK & REPAIR LH ROCKER PANEL AND REALIGN THE SAME	New	400 500.00 ✓
2	REMOVE & REFIX REAR LH DOOR GLASS	New	60.00 ✓
3	PUTTY & RESPRAY ON REAR LH DOOR, REAR LH FENDER, LH ROCKER PANEL, REAR BUMPER	New	600 950.00 ✓
4	TO RESET CENTRE LOCKING AND POWER MIRROR	New	30 50.00 ✓
Gross Labour Cost (S\$)			1,560.00

Cheng Hoe Motor Pte Ltd/SMW6356J/11/04/2023 15:58. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 3 DAYS

- NOT AUTHORISE

- EXCESS \$600

- P/P OR L/S REPAIR?

- SURVEY BY EDWARD TEL: 62563561

- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: