

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/AG/23003774/U943

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJG 9576R

at Workshop m/s 7 K here

Insured: SLV2824

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$45k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

304C

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJG 9576R Yr Regn: 22/07/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Monkg Fit c.c. 1339

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 243857 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GE 6 1087283

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10/04/23 D.O.I. 12/4/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 099k.

18/4/23 coe until 31-05-2028, LTA 819609

1/5 & 3600 in hand MIN fee (Red \$5236.08, 59%)

Date/Time, File Pass to?

1) 20/4/23

Date/Time, File Return to?

2) _____

Report Format : TP

Lump Sum / I.B.I. (\$) 3600

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

T K LEE AUTOMOTIVE PTE. LTD

NO 1 KAKI BUKIT AVE 6 #02-47
 AUTOBAY SINGAPORE 417883
 Tel : 6509 5521 / 65095524 Fax : 6509 5523
 Email: Tklee0247@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Vehicle Number: SJG9576R

Vehicle Model: HONDA FIT

PARTICULAR

QTY

LIST PRICE

AMOUNT

SS

1	FRONT BUMPER	2.5/10.1	581.30	\$	661.90	✓
1	FRONT BUMPER TOW COVER	can	20.50	\$	41.50	✓
1	FRONT BUMPER GRILLE	graze	145.20	\$	180.90	✓
1	FRONT BUMPER LOWER LIP	graze		\$	191.60	✓
1	FRONT BUMPER REINFORCEMENT	cre	298.20	\$	370.60	✓
2	FRONT BUMPER SIDE RETAINERS -R/L @ \$45.50	one		\$	91.00	✓
1	FRONT BONNET	suc		\$	591.60	✓
2	FRONT BONNET SEALS -R/L @ \$42.20	17		\$	84.40	x
1	FRONT BONNET LOCK	17		\$	110.60	x
2	FRONT BONNET HINGES -R/L @ \$55	17		\$	110.00	x
1	FRONT FENDER -LH	n		\$	580.20	x
2	FRONT FENDER INNER SHIELDS -R/L @ \$121.60	2.0.1		\$	243.20	✓
1	FRONT GRILLE	2.0.1	226.30	\$	280.90	✓
1	FRONT GRILLE LOGO	mis	38.00	\$	68.60	✓
2	FRONT HEADLAMPS -R/L @ \$1260.10	scr/cre 780 x 2 x 1580		\$	2,520.20	✓
2	FRONT HEADLAMP LOWER BRACKETS @ \$89.60	ms cre 0/5.1		\$	179.20	✓
1	FRONT SUPPORT PANEL	n		\$	560.90	✓
1	AIR CON CONDENSER	17		\$	780.60	x
1	HORN	17		\$	86.60	x
1	HORN BRACKET	17		\$	48.50	x
2	ENGINE UNDERCOVER @ \$112.30	2.0.1		\$	224.60	✓
				\$	8,007.60	
				LESS 20%	\$ 1,601.52	
					\$ 6,406.08	

SPECIAL NETT ITEMS

1	(SET) FRONT BUMPER CLIP	ner	\$	45.00	30
2	(SET) FRONT FENDER INNER SHIELD CLIPS @ \$45	17	\$	90.00	30
1	(SET) FRONT NO PLATE WITH CASING	scr	\$	65.00	40
			\$	200.00	

LABOUR CHARGES

TO CHECK FRONT ELECTRICAL WIRING	\$	50.00	20
TO REMOVE AND REPLACE A/C CONDENSER AND TOP UP GAS & OIL	\$	120.00	x
TO TUFF KOTE	\$	80.00	30
TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$	1,080.00	600
TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$	900.00	400
	\$	2,230.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 8,836.08
 4301.1
 202
 3440.88
 100
 1052.28