

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No lateral modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FBQ1923S. 2019 August.

TPECICS.

Yamaha Sniper 150 cc

Celine

MH 3U G0740K0153070

Front Fairing. ^{XP} 185 +

Front Signal Lamp. Lt 65 ✓

Side Fairing. ^{2yr} 130 +

Stickers. ^M 50(SN) ✓

Front Foot Rest ^{AP} 45 + 65 58.50
² S.N. 50

Panel Beating ~~300~~ 150

Spray Painting. ~~300~~ 100.

Wiring. ~~50~~ 30 320

To remove front camera. ~~100~~ 40.

total: 428.50

L/S: 350.

02 Dyp