



Section A - Accident Details

Registration Number	SHB5284J
Case Reference Number	TAX/04/23/2022
Registration Date	30/Nov/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHUA LAK KHOON
Type of Accident	Head to Rear
Accident Date and Time	11/Apr/2023 10:25 AM
Accident Reported Date and Time	11/Apr/2023 4:31 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118148
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	11/Apr/2023 5:48 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,602.00	\$520.00
Total Spray Cost	\$2,014.00	\$640.00
Total Spare Part Cost	\$9,017.26	\$2,249.66
Total Other Cost	\$1,335.00	\$130.00
TOTAL COST	\$13,968.26	\$3,539.66
Lump Sum Total	\$13,950.00	\$3,550.00 (L/S)
Number of Repair Days	11.0	4.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / Singapore Police Force
ARC / Surveyor Sign Off Date	14/04/2023 3:50 PM	14/04/2023 3:35 PM
Signature		
Remarks	INITIAL = 10 DAYS WITH SUPPLEMENTARY = 1 DAY TOTAL = 11 DAYS	LUMPSUM REPAIR / RESURVEY AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2305-0061	Invoice Number	
Quotation Date	07.05.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,352.00	\$400.00
TO REPAIR REAR END PANEL	\$250.00	\$120.00
Total Labour	\$1,602.00	\$520.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY BUMPER BEAM	\$220.00	\$120.00
TO RESPRAY REAR PANEL	\$220.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR SPARE TYRE PANEL	\$220.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00	\$120.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,014.00	\$640.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$475.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$50.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,335.00	\$130.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.18	Replace	Replace
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	Replace
		5246247030	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5246247020	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5246247010	PAD, RR BUMPER, RH & LH , 3	2.00	\$4.30	25.00	\$6.45	Replace	Replace

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/05/2023

User ID : PohSuan

		52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	Replace	√
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$12.30	0.00	\$0.00	Replace	Check	X
		52599680 30	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
		52575470 40	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace	Replace	√
		52591470 50	SEAL, RR BUMPER , RH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given	X
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	Replace	√
		52565479 00	FILLER, RR BUMPER , RH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X
		52566479 00	FILLER, RR BUMPER , LH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X
		52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.53	Replace	Replace	√
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X
		89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Check	X
		90189060 29	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Check	X
		81551472 81	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
		81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
		81497470 20	COVER, REAR COMBINATION LAMP, RH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X
		58398470 50	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
		58399470 30	COVER, REAR FLOOR UNDER , LH	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	X
		66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Check	X
		61601471 50	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$943.10	0.00	\$0.00	Replace	Check	X
		65637470 60	LINER, REAR FENDER , RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X
		67005474 40	TAIL GATE PANEL SUB- ASSY, BACK DOOR	0.00	\$1,238.40	0.00	\$0.00	Replace	Check	X
		67881470 50	TAIL GATE WEATHERSTRIP, BACK DOOR	0.00	\$402.50	0.00	\$0.00	Replace	Check	X
		56117501 40	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$31.10	0.00	\$0.00	Replace	Not Given	X
		76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$992.30	0.00	\$0.00	Replace	Not Given	X
		75441470 90	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
		75442471 30	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
		68105472 91	TAIL GATE GLASS SUB- ASSY, BACK DOOR	0.00	\$1,795.00	0.00	\$0.00	Replace	Not Given	X
		64801470 31	TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	0.00	\$821.20	0.00	\$0.00	Replace	Not Given	X
			SEALANT W/SCREEN (3PCS)	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
		69350470 50	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$505.50	0.00	\$0.00	Replace	Check	X
		69321470 10	TAIL GATE LOCK COVER , BACK DOOR	0.00	\$32.70	0.00	\$0.00	Replace	Not Given	X
		75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$77.40	25.00	\$58.05	Replace	Replace	√
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√
		58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Check	X
		58311471 30	SPARE TYRE PANEL , PAN, REAR FLOOR	1.00	\$630.30	100.00	\$0.00	Replace	Repair	R
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	√
Total					\$12,689.30		\$1,479.06			

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/05/2023

User ID : PohSuan

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		5256647900	FILLER, RR BUMPER , LH	1.00	\$168.60	25.00	\$126.45	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		6625947010	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace	Replace
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$127.40	25.00	\$95.55	Replace	Replace
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$992.30	25.00	\$744.23	Replace	Replace
Total					1,717.40		1,333.06		

√
√
√
√
√

	2,812.12	
	-20%	
	2249.70	L/S \$3,550/-
+	520.00	
+	770.00	
	3,539.70	