

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003777/RWP3M4
Date: 30/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00263232202		
Claimant Vehicle No :	FBP6873A	Insured Vehicle No :	SMA8294G		
Date of Loss:	19/03/2023	Nature of Claim:	TP	Claim No:	SNM23D202646/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP6873A		Engine No:	NC42E5200050
Make & Model:	HONDA CB400A, 399cc		Chassis No:	JH2NC4296KK500047
Reg. Date:	17/05/2019 (Man. Year: 2019)		Odometer:	28098 km
Colour:	Multi-colour			
Engine Capacity:	399 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60ZR17	Rear Tyre Size:	160/60ZR17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,471.40	6,293.40	2,178.00	25.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	530.00	450.00	45.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,451.40	6,823.40	2,628.00	27.81
+ GST 8.00/8.00% (S\$)	756.11	545.87	210.24	27.81
Nett Amount (S\$)	10,207.51	7,369.27	2,838.24	27.81

INSPECTION

Date of Assignment:	11/04/2023		
Date Inspected:	11/04/2023	Inspected At:	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$40.00 NETT)

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 30 May 2023)	
Parts:	N/A	HONDA CB400A 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP6873A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE LEVER	Scratched	85.00 FL	*85.00 FL
2	1		*HANDLE BAR	Bent	160.00 FL	*160.00 FL
3	1		*SET MIRROR	Scratched	98.00 FL	*98.00 FL
4	1		*HANDLE BALANCER	Scratched	45.00 FL	*45.00 FL
5	1		*SET METER	Scratched	1,880.00 FL	*1,880.00 FL
6	1		*ENGINE GUARD	Bent	160.00 FL	*160.00 FL
7	1		*EXHAUST PIPE	Bent	1,450.00 FL	*1,450.00 FL
8	1		*REAR SIGNAL	N/S Cracked	180.00 FL	*90.00 FL
9	1		*REAR HEADLAMP	Broken	380.00 FL	*380.00 FL
10	1		*REAR TAIL COVER	Cracked	450.00 FL	*450.00 FL
11	1		*FOOTREST BRACKET	Bent	295.00 FL	*295.00 FL
12	1		*REAR BRAKE DISK	Scratched	280.00 FL	*280.00 FL
13	1		*REAR NUMBER PLATE LIGHT	Broken	68.00 FL	*68.00 FL
14	1		*REAR MUDGUARD	Deformed	135.00 FL	*135.00 FL
15	1		*REAR BOX	Scratched	250.00 FL	*250.00 FL
16	1		*REAR BOX BRACKET	Not Necessary	180.00 FL	*- FL
17	1		*REAR SPORT RIM	Scratched	1,150.00 FL	*1,150.00 FL
18	1		*REAR SWING ARM	Repair	1,100.00 FL	*- FL
19	1		*REAR FORK	Not Necessary	1,050.00 FL	*- FL
20	1		*NUMBER PLATE	Bent	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,411.00	6,991.00
- List Item Discount on L Items 10.00/10.00% (S\$)	939.60	697.60
Total Parts (S\$)	8,471.40	6,293.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING * Check	New	40.00	0.00
2	JACK REAR BODY	New	380.00	280.00
3	ALIGNMENT FORK	New	180.00	0.00
4	LABOUR	New	380.00	250.00
			Gross Labour Cost (S\$)	980.00
				530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >