

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23003778/TVY3Q2**Date:** 05/05/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000815
Claimant Vehicle No :	SHD6699D	Insured Vehicle No :	SNH1816Z
Date of Loss:	10/04/2023	Nature of Claim:	TP
		Claim No:	M2302344

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6699D	Engine No:	2ZR2G82079
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU303091567
Reg. Date:	30/09/2020 (Man. Year: 2020)	Odometer:	174054 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	T195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,299.55	3,693.18	606.37	14.10
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,970.00	970.00	1,000.00	50.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,280.55	4,674.18	1,606.37	25.58
+ GST 8.00/8.00% (S\$)	502.45	373.93	128.52	25.58
Nett Amount (S\$)	6,783.00	5,048.11	1,734.89	25.58

INSPECTION

Date of Assignment:	12/04/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	12/04/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount:\$4,674.17

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2023)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6699D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	52.40 FL	*52.40 FL
2	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	52.90 FL	*52.90 FL
3	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	60.80 FL	*60.80 FL
4	1		*REAR TRUNK LID GARNISH OUTSIDE	Cracked	1,054.71 FL	*1,054.71 FL
5	1		*TAIL LAMP LOWER LH	Not Necessary	570.00 FL	*- FL
6	1		*TAIL LAMP SIDE LH	Cracked	256.00 FL	*256.00 FL
7	1		*REAR BUMPER	Deformed	551.89 FL	*551.89 FL
8	1		*REAR BUMPER CENTRE MOULDING	Deformed	654.96 FL	*654.96 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	378.32 FL	*378.32 FL
10	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
11	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	110.00 FL	*- FL
12	1		*REAR BUMPER TOW COVER RH	Deformed	82.70 FL	*82.70 FL
13	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	225.40 FL	*- FL
14	1		*REAR REVERSE SENSOR	Not Working	135.70 FL	*135.70 FS
15	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
16	1		*REAR NUMBER PLATE W/HOLDER	Bent	55.00 FL	*55.00 FS
17	1		*BOOTLID COMFORT /TEL NUMBER STICKER	Necessary	60.00 FL	*60.00 FS
18	1		*BOOTLID COMFORT APP STICKER	Necessary	40.00 FL	*40.00 FS

Supplementary #1

19	1		*REAR TRUNK LID	Bent	1,303.29 FL	*1,303.29 FL
----	---	--	-----------------	------	-------------	--------------

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,716.07	4,810.67
- List Item Discount on L Items 25.00/25.00% (S\$)	1,416.52	1,117.49
Total Parts (S\$)	4,299.55	3,693.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	350.00
2	SPRAY PAINTING	New	800.00	500.00
3	CHECK WIRING/ LIGHTING	New	60.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
5	TUFF KOTE	New	90.00	0.00
6	TOWING FEE	New	60.00	60.00
Gross Labour Cost (\$\$)			1,970.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >