

ASS. REC. BY: Taught

REF:

CS/ TU1 23003778/Tvy3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: **SNH 1816Z**
Policy No. **MN000815**
Claims No. **M2302344**
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
☒	☒

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD6699D Yr Regn: 2020 Sep
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota Prius c.c. 1798
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 174054 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 510KBBF4303091567
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: NI / S/Rim / STD A/Rim or _____
Tyre Size: F: 195/65R15
R: 7
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Wishbone
Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 10/4/2023 D.O.I. 12/4/23
Survey held at Comfort Lodge
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
3/5/23	Final fig \$4674.17 confirmed by email (Red 1606.38, 25%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 3/5/23-typist

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Rep. Format: Merimen

Lump Sum / L.B. (\$ \$4674.17)

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

HKK

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	10/04/2023
Vehicle Reg. No.:	SHD6699D	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Vehicle Reg. Date:	30/06/2020
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2G82079	Chassis No:	JTDKB3FU303091567
Odometer:	174054 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	3,322.08
Miscellaneous Items	11.00
Labour	1,970.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,303.08
+ GST 8.00% (S\$)	424.25
Nett Amount (S\$)	5,727.33

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 11 Apr 2023)**Parts:** 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD6699D/11/04/2023 15:04**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR TRUNK LID LOGO (HYBRID)	25.00	0.00 <i>rel</i>	*52.40 FL
2	1		*REAR TRUNK LID LOGO (PRIUS)	25.00	0.00 <i>rel</i>	*52.90 FL
3	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	25.00	0.00 <i>X</i>	*60.80 FL
4	1		*REAR TRUNK LID GARNISH OUTSIDE	25.00	0.00 <i>rel</i>	*1,054.71 FL
5	1		*TAIL LAMP LOWER LH	25.00	0.00 <i>?</i>	*570.00 FL
6	1		*TAIL LAMP SIDE LH	25.00	0.00 <i>?</i>	*256.00 FL
7	1		*REAR BUMPER	25.00	0.00 <i>rel</i>	*551.89 FL
8	1		*REAR BUMPER CENTRE MOULDING	25.00	0.00 <i>rel</i>	*654.96 FL
9	1		*REAR BUMPER REINFORCEMENT	25.00	0.00 <i>?</i>	*378.32 FL
10	10		*REAR BUMPER CLIPS	25.00	0.00 <i>rel</i>	*22.00 FL
11	2		*REAR BUMPER REFLECTOR LH/RH	25.00	0.00 <i>X</i>	*110.00 FL
12	1		*REAR BUMPER TOW COVER RH	25.00	0.00 <i>rel</i>	*82.70 FL
13	2		*REAR BUMPER SIDE RETAINER LH/RH	25.00	0.00 <i>?</i>	*225.40 FL
14	1		*REAR REVERSE SENSOR	25.00	0.00 <i>rel</i>	*135.70 FL
15	1		*REAR BUMPER MAT	0	0.00 <i>rel</i>	*50.00 FS
16	1		*REAR NUMBER PLATE W/HOLDER	25.00	0.00 <i>bt</i>	*55.00 FL
17	1		*BOOTLID COMFORT /TEL NUMBER STICKER	25.00	0.00 <i>rel</i>	*60.00 FL
18	1		*BOOTLID COMFORT APP STICKER	25.00	0.00 <i>rel</i>	*40.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	4,412.78
- List Item Discount on L Items (\$\$)	1,090.70
Total Parts (\$\$)	3,322.08

ComfortDelGro Engineering Pte Ltd/SHD6699D/11/04/2023 15:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New 350	900.00
2	SPRAY PAINTING	New 500	800.00
3	CHECK WIRING/ LIGHTING	New 30	60.00
4	REMOVE/REFIX REVERSE SENSOR	New 30	60.00
5	TUFF KOTE	New X	90.00
6	TOWING FEE	New towing receipt	60.00
Gross Labour Cost (\$\$)			1,970.00

ComfortDelGro Engineering Pte Ltd/SHD6699D/11/04/2023 15:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanji 97495744
wp 12/4/23 430pm
Tanji C/WhatsApp
2-3 days
P/R. Repair before paint

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental parts must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

Date/Time: 11.04.2023 13:41

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5892651

JC NO305550946


CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)		REGN NO: SHD6699D	MILEAGE
		MAKE: TOYOTA	FUEL E.....1/2.....F
		MODEL PRIUS HYBRID(G4A10.04.2023 20:35	DATE/TIME IN
		YR OF MANU 30.09.2020	TARGET DATE
COUNT CARD NO.		CHASSIS CODE JTDKB3FU303091567	COMPLETION DATE/TIME:

Accident Date: 10.04.2023

Incident Nature: 3P 10.04.2023

JOB DESCRIPTION

Sl/NO LABOR CODE DESCRIPTION



Checked & Passed Out By:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Vehicle Identification Slip

Exit Pass

No.: SHD6699D

CHIANG

Vehicle No.:

SHD6699D

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard