

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23003779/TNY3Q2**Date:** 19/04/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP005482		
Claimant Vehicle No :	SHA1801Z	Insured Vehicle No :	SLR9120R		
Date of Loss:	09/04/2023	Nature of Claim:	TP	Claim No:	M2302329

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1801Z	Engine No:	2ZR2B82764
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU903077625
Reg. Date:	06/12/2018 (Man. Year: 2018)	Odometer:	678781 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,889.28	700.93	2,188.35	75.74
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,560.00	880.00	680.00	43.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,460.28	1,591.93	2,868.35	64.31
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	4,460.28	1,250.00	3,210.28	71.97
+ GST 8.00/8.00% (S\$)	356.82	100.00	256.82	71.97
Nett Amount (S\$)	4,817.10	1,350.00	3,467.10	71.97

INSPECTION

Date of Assignment:	12/04/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	12/04/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2023)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1801Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID (PRIUS)	Necessary	62.14 FL	*62.14 FL
2	1		*BOOTLID (HYBRID)	Necessary	62.14 FL	*62.14 FL
3	1		*BOOTLID (TOYOTA STAR)	Not Necessary	81.43 FL	*- FL
4	1		*REAR BUMPER	Repair	503.04 FL	*- FL
5	1		*REAR BUMPER CENTRE MOULDING	Deformed	654.96 FL	*654.96 FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REAR BUMPER TOW COVER	Not Necessary	82.70 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	378.32 FL	*- FL
9	1		*TAILLAMP LOWER RH (Not Necessary)	Not Consistent With The Impact	570.00 FL	*- FL
10	1		*BOOTLID (COMFORTDELGRO)	Necessary	30.00 F	*30.00 F
11	1		*BOOTLID (65521111)	Necessary	30.00 F	*30.00 F
12	1		*BOOTLID (ZIG)	Necessary	40.00 F	*40.00 F
13	1		*REAR BUMPER MAT	Not Necessary	50.00 F	*- F
14	1		*REVERSE SENSORS	Not Necessary	135.70 F	*- F
15	1		*BOOTLID OUTER GARNISH	Repair	1,054.71 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	3,757.14 901.24
					- List Item Discount on L Items 25.00/25.00% (S\$)	867.86 200.31
					Total Parts (S\$)	2,889.28 700.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	CHECK LIGHTINGS	New	40.00	0.00
4	R/I REVERSE SENSORS	New	120.00	30.00
Gross Labour Cost (\$\$)			1,560.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >