

ASS. REC. BY: Taufikh

REF:


CS/TMI23003779/Tny3

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 2 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SN71801Z Yr Regn: 2018 Dec  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Toyota Prius c.c. 1798  
Colour: Blue A/C: Insured / Std / NI / NA  
Sp. Reading: 678781 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JTBKBS3F4903077625  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 195/65R15  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Westlake  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 12/4/23  
Survey held at Changkat Geyang  
Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh confirmed lump sum lump sum \$1250, 2 days.  
(red, \$3210.28, 72%)

Date/Time, File Pass to?

1) 17/04/2023

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / L.B.A. (\$) \_\_\_\_\_

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

Lim Tien Siong

**TP INSURER:**  
**CTPL**

**Tokio Marine Insurance Singapore Ltd (HQ)**

Singapore

LKK-

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	09/04/2023
Vehicle Reg. No.:	SHA1801Z	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Vehicle Reg. Date:	06/12/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2B82764	Chassis No:	JTDKB3FU903077625
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

**COST OF CLAIMS**

	Amount
Parts	2,889.28
Miscellaneous Items	11.00
Labour	1,560.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>4,460.28</b>
<b>+ GST 8.00% (\$\$)</b>	<b>356.82</b>
<b>Nett Amount (\$\$)</b>	<b>4,817.10</b>

**This claim is handled by: LIM TIEN SIONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

11/4 @ 08:56 hrs

## REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Apr 2023)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA1801Z/11/04/2023 08:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Lim Tien Siang

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID (PRIUS)	25.00	0.00	all ✓ *62.14 FL
2	1		*BOOTLID (HYBRID)	25.00	0.00	all ✓ *62.14 FL
3	1		*BOOTLID (TOYOTA STAR)	25.00	0.00	X ✓ *81.43 FL
4	1		*REAR BUMPER	25.00	0.00	Ry ✓ *503.04 FL
5	1		*REAR BUMPER CENTRE MOULDING	25.00	0.00	all ✓ *654.96 FL
6	10		*REAR BUMPER CLIPS	25.00	0.00	all ✓ *22.00 FL
7	1		*REAR BUMPER TOW COVER	25.00	0.00	*82.70 FL
8	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	? *378.32 FL
9	1		*TAILLAMP LOWER RH <i>Not consistent</i>	25.00	0.00	X ✓ *570.00 FL
10	1		*BOOTLID (COMFORTDELGRO)	0.00	0.00	all ✓ *30.00 F
11	1		*BOOTLID (65521111)	0.00	0.00	all ✓ *30.00 F
12	1		*BOOTLID (ZIG)	0.00	0.00	all ✓ *40.00 F
13	1		*REAR BUMPER MAT	0.00	0.00	X ✓ *50.00 F
14	1		*REVERSE SENSORS	0.00	0.00	? *135.70 F
15	1		*BOOTLID OUTER GARNISH	25.00	0.00	Ry ✓ *1,054.71 FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	3,757.14
- List Item Discount on L Items (S\$)	867.86
Total Parts (S\$)	2,889.28

ComfortDelGro Engineering Pte Ltd/SHA1801Z/11/04/2023 08:56. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS



# Estimates on Miscellaneous Items

No Qty Particulars

Amount

## Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

# Estimates on Labour

No Particulars

Lab.Type

Amount

## Labour Items

1	PANEL BEATING	New	350	800.00
2	SPRAY PAINTING	New	500	600.00
3	CHECK LIGHTINGS	New	X	40.00
4	R/I REVERSE SENSORS	New	30	120.00
Gross Labour Cost (S\$)				1,560.00

ComfortDelGro Engineering Pte Ltd/SHA1801Z/11/04/2023 08:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanjin 97495744  
 WP 12/4/23 430  
 L/S rising after repair  
 tanglin chuan tan  
 2 days, 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 5892559

JC NO305550924


OMER	REGN NO. SHA1801Z	MILEAGE
S COMFORT TRANSPORTATION PTE LTD	MAKE TOYOTA	FUEL
OMER NO 7010045	MODEL PRIUS HYBRID(G4)10.04.2023 12:15	E.....1/2.....F
IESS 383 SIN MING DRIVE	YR OF MANU. 06.12.2018	DATE/TIME IN
Singapore SINGAPORE 575717	CHASSIS CODE JTDKB3FU903077625	TARGET DATE
65508755 (R) (O)		COMPLETION DATE/TIME:
DUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 09.04.2023  
ATURE: 3P 09.04.2023

'NO LABOR CODE  
00010 PB

DESCRIPTION  
PANEL BEATING-SHA1801Z-TP



KED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHA1801Z LIMTS

Vehicle No.: SHA1801Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard