

ASS. REC. BY: Tajir

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____



Vehicle: IN / OUT

Veh No: SN 718012 Yr Regn: 2018 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 678781 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JBKRB3FY903077625

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 12/4/23

Survey held at Compass Agency

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B. ()

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS. ____ SI

Photos

Others

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	09/04/2023
Vehicle Reg. No.:	SHA1801Z	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Vehicle Reg. Date:	06/12/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2B82764	Chassis No:	JTDKB3FU903077625
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,889.28
Miscellaneous Items	11.00
Labour	1,560.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,460.28
+ GST 8.00% (S\$)	356.82
Nett Amount (S\$)	4,817.10

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

11/4 @ 08:56 hrs

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2023)	Lim Tien Siong
Parts: 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: ComfortDelGro Engineering Pte Ltd/SHA1801Z/11/04/2023 08:56		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID (PRIUS)	25.00	0.00	all *62.14 FL
2	1		*BOOTLID (HYBRID)	25.00	0.00	all *62.14 FL
3	1		*BOOTLID (TOYOTA STAR)	25.00	0.00	X *81.43 FL
4	1		*REAR BUMPER	25.00	0.00	Ry *503.04 FL
5	1		*REAR BUMPER CENTRE MOULDING	25.00	0.00	all *654.96 FL
6	10		*REAR BUMPER CLIPS	25.00	0.00	all *22.00 FL
7	1		*REAR BUMPER TOW COVER	25.00	0.00	*82.70 FL
8	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	? *378.32 FL
9	1		*TAILLAMP LOWER RH <i>Not consistent</i>	25.00	0.00	X *570.00 FL
10	1		*BOOTLID (COMFORTDELGRO)	0.00	0.00	all *30.00 F
11	1		*BOOTLID (65521111)	0.00	0.00	all *30.00 F
12	1		*BOOTLID (ZIG)	0.00	0.00	all *40.00 F
13	1		*REAR BUMPER MAT	0.00	0.00	X *50.00 F
14	1		*REVERSE SENSORS	0.00	0.00	? *135.70 F
15	1		*BOOTLID OUTER GARNISH	25.00	0.00	Ry *1,054.71 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,757.14
- List Item Discount on L Items (S\$)	867.86
Total Parts (S\$)	2,889.28

ComfortDelGro Engineering Pte Ltd/SHA1801Z/11/04/2023 08:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Lim Tien Siong

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

350

800.00

2 SPRAY PAINTING

New

500

600.00

3 CHECK LIGHTINGS

New

X

40.00

4 R/I REVERSE SENSORS

New

30

120.00

Gross Labour Cost (\$\$)

1,560.00

ComfortDelGro Engineering Pte Ltd/SHA1801Z/11/04/2023 08:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanjin 97495744
WP 12/4/23 430
L/S rising after repair
taughtin e/hand down
2 days 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609886

Date/Time: 11.04.2023 08:19 Page : 1


am: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 5892559 JC NO305550924

OMER	REGN NO: SHA1801Z	MILEAGE
S COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL
OMER NO 7010045	MODEL	E.....1/2.....F
IESS 383 SIN MING DRIVE	PRIUS HYBRID(G4)10.04.2023 12:15	DATE/TIME IN
Singapore SINGAPORE 575717	YR OF MANU 06.12.2018	TARGET DATE
65508755 (R) (O)	CHASSIS CODE JTDKB3FU903077625	COMPLETION DATE/TIME:
(P)		
DUNT CARD NO.		

Accident Date: 09.04.2023
ATURE: 3P 09.04.2023

LABOR CODE PB

DESCRIPTION
PANEL BEATING-SHA1801Z-TP



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vehicle No.: SHA1801Z

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard