

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2045Y

08.04.2023

MAKE REG. 14.11.2019

CHIANG/1NCOME

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER <i>Repair</i>		\$459.40 X
1	REAR BUMPER SIDE BRACKET LH <i>2. X 17</i>		\$55.80 X
1	REAR BUMPER REINFORCEMENT <i>2. X 17</i>		\$394.80 X
2	REAR BUMPER REINFORCEMENT LH/RH <i>2. X 17</i>		\$138.10 X
1	REAR BUMPER CENTRE MOULDING <i>See</i>		\$451.25
1	REAR TOW COVER <i>X 17</i>		\$38.80 X
10	REAR BUMPER CLIPS <i>See</i>		\$2.20
	SUB TOTAL		\$1,698.25
	20.00%		\$339.65
	DISCOUNTED TOTAL		\$1,358.60
1	REAR NUMBER PLATE W/HOLDER <i>See</i>		\$55.00
1	REAR BUMPER MAT <i>X 17</i>		\$50.00
1	REAR REVERSE SENSOR <i>X 17</i>		\$180.00
			\$261.50
	Labour Charge		
	Panel Beating		350 \$600.00
	Spray Painting Charge		280 \$300.00
	Check Lighting and Wiring		11X \$60.00
	Remove/refix Reverse sensor		11X 40? \$80.00
	TOTAL LABOUR		\$1,020.00
	ESTIMATE TOTAL		\$2,640.10
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2094.68

1033.60

3128.28

20%

2502.62

45-\$2,500

5 days

PASEL

Hp 90010068

3 days

43

10/04/23 @ 1630

Resurvey after repair

10/04 Survey by Rasul Rear portion

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2045Y
MAKE REG. 14.11.2019
MODEL IONIQ G3

08.04.2023

Supplementary - Front portion

CHIANG/ INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER XR			Rx \$481.10
1	FRONT BUMPER BRACKET TOP RH X ^{an}		\$35.00	? \$350.00
1	FRONT BUMPER GRILLE LH X ^{an}			x \$186.50
10	FRONT BUMPER CLIPS re/		\$2.20	key - \$22.00
1	FRONT BUMPER MOULDING ut/			ut \$368.50
1	FRONT RADIATOR GRILLE ca/			ca? \$1,409.10
	SUB TOTAL			\$2,817.20
	20.00%			\$563.44
	DISCOUNTED TOTAL			\$2,253.76
1	FRONT NUMBER PLATE		55	Cur \$55.00
				\$49.50
	Labour Charge			
	Panel Beating		350	\$550.00
	Spray Painting Charge		250	\$300.00
	Check Wiring			X ^{an} \$60.00
	TOTAL LABOUR			\$910.00
	ESTIMATE TOTAL			\$3,213.26

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

-2 days