



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD
79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT
TEL : FAX :

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 02/04/2023

ESTIMATE

NO : QUOT202304-000028(00)
DATE : 12/04/2023
POLICY NO : SP2003902365
VEH REG NO : GBL5879L
MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR
CHASSIS NO : W1V44760323891533
ENGINE NO : 65195035425360
REG. DATE : 2021

Estimate Repair Cost to Vehicle No : GBL5879L

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Support panel holder - LH	1	23.00	23.00
2 Front fender signal lamp - LH	1	22.00	22.00
3 Front wheel rim - LH	1	190.00	190.00
4 Oil dipstick tube	1	118.00	118.00
			353.00
		Add 10%	35.30
			388.30
		TOTAL	S\$ 388.30
		ADD GST @ 8%	31.06
		GRAND TOTAL	S\$ 419.36

SINGAPORE DOLLAR FOUR HUNDRED NINETEEN AND CENTS THIRTY-SIX ONLY

Parts : \$ 5,337.20
SN : 55.00
Labour : 2,020.00
Supp : 388.30
XS \$ 7,800.50
900.00
\$ 6,900.50
8% 552.04
\$ 7,452.54

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE