REF: AIS/ 230037941KV ASS. REC. BY: Tenneth ASSIGNMENT GBL 5879L Yr Regn: 11, 21 From: Veh No: Estimated Cost: DO ITP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or To Inspect Vehicle No: Make: at Workshop m/s Colour Insured / Std / NI / NA Sp.Reading T/Radio: Insured / Std / N1 / NA Insured: Eng/No: Policy No. SP2003902365 WIV44760323891533 C/No: Claims No. 202332006900 Gen. Cond: Good / Fair / Poor / Burnt Sum Insured: 900 Steering: Inoreer / Jammed / Leaked / Burnt or Excess: (Client's Record) Brake: Inerder / Jammed / Leaked / Burnt or Make of Veh: MIT I SIRIM I STD AIRIM OF Tyre Size: (Policy Condition) Pamark: The veh had commenced its NVS O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO/YOKO or Bal, or Market Value: Front Rear IDAC Accident Rport: Consistent?: Yes or No R/Bal R/Bal GIA / PR Seen: Consistent?: Yes or No L/Bal. L/Bal Est. Repairs: Res.: Yes or No D.O.A. 1-13.1 % Lum Sum: CA / REV / REP. / 24 HRS Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Vehicle: IN/OUT Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction 31/5/23 Final fig \$7800.50 confirmed by email (red 5094.80, 39%) Dato/Time, File Pass to? : Prell. Report Days Of Repair: 9 : Final Report Resurvey No. of Trip: 1 Survey Fee: Outa/Time, File Return to? Transportation 2 31/5/23-typist Add Fee: : Site Insp (\$ __ S - RS.__SI Interview (\$ Report Format: Merimen Tech Invs (\$ Others Lump Sum / I.B.I: (\$ 7800.50 Weekend (\$

11.74

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 778Z

Vehicle Details

PARF Rebate Amount:

Vehicle No.: GBL5879L
Vehicle to be Exported: No

Intended Deregistration Date: 30 Jun 2023
Vehicle Make: MERCEDES BENZ

Vehicle Model: VITO 114 CDI PANEL VAN LONG AT ABS 5DR

Primary Colour: White
Manufacturing Year: 2021

Engine No.: 65195035425360
Chassis No.: W1V44760323891533

Chassis No.: W1V44760323891

Maximum Power Output: -

Open Market Value:\$32,999.00Original Registration Date:05 Nov 2021First Registration Date:05 Nov 2021

Transfer Count: 0
Actual ARF Paid: \$1,650.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -

Intended COE Rebate Details

COE Expiry Date: 04 Nov 2031
COE Category: C - Goods Vehicle & Bus

 COE Period(Years):
 10

 QP Paid:
 \$39,000.00

 COE Rebate Amount:
 \$32,543.00

Total Rebate Amount: \$32,543.00

The information contained herein is correct as at 12 Apr 2023

\$0.00



Allianz Insurance Singapore Pte. Ltd.

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION) (REPUBLIC OF SINGAPORE)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 (REPUBLIC OF SINGAPORE)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Certificate Number : SP20039023

Date of Issue : 27 December 2022

Coverage : COMPREHENSIVE - AUTHORISED WORKSHOP

Policyholder : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE. LTD.

Finance Company :

Period of Insurance : 01 January 2023 To 31 December 2023 (both dates inclusive)

Registration Number : GBL5879L

Chassis Number of Vehicle : W1V44760323891533

Persons or Classes of Persons Entitled to Drive*:

(a) The Policyholder.

- (b) Any other person who is driving on the Policyholder's order or with his/her permission or to whom the
- * Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulations in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act (Cap 276) (Republic of Singapore) and such registration has not been cancelled at the time of accident loss or damage.

Limitation as to Use^:

- (a) Use for carriage of passengers or goods in connection with the Policyholder's business.
- (b) Use for social, domestic and pleasure purposes and business purposes of any person to whom the vehicle is hired.
- Limitation rendered inoperative by Section 8 of Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Policy does not cover:

- (a) Use for racing, pace-making, reliability trials or speed-testing.
- (b) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.
- (c) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act,1987 (Malaysia).

27 December 2022

Issue Date

Hicham Raissi

Chief Executive Officer
Allianz Insurance Singapore Pte. Ltd.

Intermediary Code : 0000256 M

: 0000256 MARSH (SINGAPORE) PTE. LTD.

Excess

: Section 1: Own Damage


Section 1: Windscreen

S\$ S\$ 900.00

Section 2: Liabilities to Third Parties

S\$

0.00





5J0G2343001U / JP Knights Pte Ltd ENTRY DATE & TIME: 03/04/2023 15:58 (SGT) SUBMITTED BY: Siti VERSION: 1 (03/04/2023 15:58 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation. 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

03/04/2023 15:58 (SGT) Actual Driver 02/04/2023 09:00 (SGT) Woodlands Street 31, Singapore NEXT TO BLK 343 OSCP Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBL5879L

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No **Email Address** Mobile Phone No Alternative Phone No

MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE

LTD

too tong.tan@mercedes-benz.com

(Phone) +65-88511742 (Office) +65-82821711

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

CC

Mercedes

Vito

Employment

Yes

Commercial vehicle

Auto 2143

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number Allianz Insurance Singapore Pte. Ltd. SP2003902365

DRIVER

Name of Driver NRIC No Date Of Birth

MOHAMMAD NOH BIN OSMAN SXXXX586Z 30/08/1974

Occupation

Date Of Driving Pass

Driving experience

Gender

Mobile Number

Alt. Phone Number Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

Outdoor 28/11/2016

6 YEARS AND 5 MONTHS

Male

(Phone) +65-88511742

too_tong.tan@mercedes-benz.com 38 BEDOK SOUTH ROAD #04-653

460038

No

Hirer

No

-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident

Weather Conditions

Road Surface

Collided into Parked Vehicle

Clear

Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

Translator's name

Translator's ID

Translator's phone number

Translator's email

Original language used in the statement

No

3 No

INU

Yes 1

No

.

-

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

If yes, against whom?

No No

CIRCUMSTANCES OF ACCIDENT

ON O2/04/2023 AROUND 0900HRS I VEHICLE A BEARING REGISTRATION NUMBER (GBL5879L) WAS DRIVING AT WOODLAND STREET 31 NEXT TO BLOCK 343 OSCP, AS I WAS LOOKING FOR A PARKING SLOT TO PARK VEHICLE (A) ACCIDENTALLY OVER STEER AND COLLIDED TO PARKED VEHICLE BEARING REGISTRATION NUMBER (YP6331A) AND THE FORCE OF IMPACT MADE VEHICLE (B) MOVED AND HIT ANOTHER VEHICLE C BEARING REGISTRATION NUMBER (SNB4862B) WHICH WAS NEXT TO VEHICLE (B).

I COULDN'T GET THE VEHICLE (B) CONTACT DETAILS AS THE DRIVER WAS NOT AROUND, BUT I DO ABLE TO EXCHANGE PARTICULARS WITH THE VEHICLE (C) DRIVER, NO INJURIES HAPPEND DURING THE ACCIDENT.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YP6331A



Vehicle Manufacturer Isuzu Vehicle Model Vehicle Variant Vehicle Colour Commercial vehicle Vehicle Category Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

SNB4862B Vehicle Registration Number Vehicle Manufacturer Honda Vehicle Model Vehicle Variant Vehicle Colour Blue Vehicle Category Private car MOI WENG KEONG, EDWIN Name of Driver NRIC No SXXXX964B (Phone) +65-84392939 Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any willful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set, out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(Collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sted outside of Singapore, for one or more of the above Purposes.

FLASH ACCIDENT CODE OF THE REPORTING OFFICER FRO VICKY

Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyholder) / Date & Time 02042023 — 1430 Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

ON 02/04/2023 AROUND 0900HRS I VEHICLE A BEARING REGISTRATION NUMBER (GBL5879L) WAS DRIVING AT WOODLAND STREET 31 NEXT TO BLOCK 343 OSCP, AS I WAS LOOKING FOR A PARKING SLOT TO PARK VEHICLE (A) ACCIDENTALLY OVER STEER AND COLLIDED TO PARKED VEHICLE BEARING REGISTRATION NUMBER (YP6431A) AND THE FORCE OF IMPACT MADE VEHICLE (B) MOVED AND HIT ANOTHER VEHICLE C BEARING REGISTRATION NUMBER (SNB4862B) WHICH WAS NEXT TO VEHICLE (B) I COULDN'T GET THE VEHICLE (B) CONTACT DETAILS AS THE DRIVER WAS NOT AROUND, BUT I DO ABLE TO EXCHANGE PARTICULARS WITH THE VEHICLE (C) DRIVER, NO INJURIES HAPPEND DURING THE ACCIDENT.

Declaration

I'We declare the foregoing particulars are true in every respect.



FLASH ACCIDENT

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date 8. Time 02042023 —— 1430 Witnessed by Reporting Centre Personnel



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01 Not Norther 1

Rearry B& pains

ATTN: MOTOR CLAIMS DEPT

30 Front door "company" sticker

FAX:

YOUR REF NO CLAIM TYPE

: OWN DAMAGE

ACCIDENT DATE : 02/04/2023

ESTIMATE

: QUOT202304-000028(00) NO

DATE : 12/04/2023

POLICY NO

: SP2003902365

VEH REG NO : GBL5879L

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI PANEL VAN LONG AT ABS 5DR

25.00 1 25.00 -

: W1V44760323891533

CHASSIS NO **ENGINE NO**

: 65195035425360

REG. DATE

: 2021

Estimate Repair Cost to Vehicle No: GBL5879L

	Description	Quantity	Unit Price		Amount		
				<u>\$\$</u>		<u>S\$</u>	
200	PARTS			950.00	B	950.00	_
1	Bonnet	ols Dil 2	NISR	85.00		170.00	L
2	Bonnet hinges - RH / LH	2.3 0. 2			a	115.00	,
3	Bonnet lock	1		115.00	- 2	45.00	×
4	Bonnet catch	1		45.00		98.00	-
5	Bonnet pull handle	1		98.00			1
6	Bonnet cable	1		48.00		48.00	
7	Support panel	1		325.00	CAS		
8	Support panel top garnish	1		78.00		78.00	-
9	Support panel top bracket - RH / LH	1		23.00		23.00	- 10
10	Brace panel	1		88.00		88.00	
11	Headlamp assy - LH	1		580.00		580.00	
12	Front bumper	1		780.00		780.00	
13	Front bumper reinforcement	1		620.00		620.00	1
14	Front bumper side retainer - LH	1		58.00	cm	58.00	
15	Front bumper inner carrier - LH	1		115.00		115.00	L
16	Front bumper centre logo	1		92.00	nec	92.00	_
17	Front bumper support - LH	1	100	58.00		58.00	-
18	Support panel side sponge - LH	1		24.00		24.00	
19	Front bumper holder - LH	1		24.00		24.00	
20	Front bumper lower frame	1		226.00		226.00	
21	Front bumper under cover	1		112.00	sn	112.00	
22	Front grille inner support	1		480.00		480.00	
23	Front fender - LH	1		590.00	Ry	590.00	_
24	Front fender wheel house extension member- LH	1	480	780.00	By	780.00	-
25	Front fender inner shield - LH	1		125.00	cru	125.00	L
26	Front fender inner shield cover - LH	1		30.00	m	30.00	,
27	Front fender rail - LH	1		12.00	nii	12.00	1
	Front fender - LH	1	Reporter	1,050.00	1.	050.00	
	Front door hinges - LH	2	2	112.00	R	224.00	X
				Add 10%		970.00 742.00	85
					8,	712.00	
	SPECIAL NET						



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79. ROBINSON ROAD #09-01

SINGAPORE 068897

ATTN: MOTOR CLAIMS DEPT

TEL :

FAX:

YOUR REF NO

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 02/04/2023

ESTIMATE

NO

: QUOT202304-000028(00)

DATE

: 12/04/2023

POLICY NO

: SP2003902365

VEH REG NO : GBL5879L

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI

PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323891533

ENGINE NO : 65195035425360

REG. DATE

: 2021

Estimate Repair Cost to Vehicle No: GBL5879L

Description	Quantity	Unit Price	Amount	
		<u>S\$</u>	<u>S\$</u>	
Front quater glass sealant - LH	1	40.00	Ma 40.00	305
			65.00	
LABOUR				401
To remove and refit LH quater glass to facilitates the repairs	1	80.00	80.00	
To transfer LH front door interior mechanism and glass to new	1	150.00	nn 150.00	X
To check and rectify wiring system	1	80.00	80.00	201
To panel beat and straighten LH front fender inner panel, LH front chassis frame, LH front door pillar, to cut and weld LH front wheel	1	1,800.00	1,800.00	1100
			de	201
To putty and spray paint on affected areas	1	1,500.00	1,500.00	
To compterise check wheel alignment	1	120.00	120.00	60
			3,730.00	
		TOTAL	\$\$ 12,507.00	
	AL	DD GST @ 8%	1,000.56	
	G	RAND TOTAL	S\$ 13,507.56	
	LABOUR To remove and refit LH quater glass to facilitates the repairs To transfer LH front door interior mechanism and glass to new door To check and rectify wiring system To panel beat and straighten LH front fender inner panel, LH front chassis frame, LH front door pillar, to cut and weld LH front wheel house extension member, including replacement of parts and align where necesary, to refit and adjust the same To putty and spray paint on affected areas	Front quater glass sealant - LH LABOUR To remove and refit LH quater glass to facilitates the repairs 1 To transfer LH front door interior mechanism and glass to new door To check and rectify wiring system 1 To panel beat and straighten LH front fender inner panel, LH front chassis frame, LH front door pillar, to cut and weld LH front wheel house extension member, including replacement of parts and align where necesary, to refit and adjust the same To putty and spray paint on affected areas 1 To compterise check wheel alignment ALI ALI ALI ALI ALI ALI ALI AL	Front quater glass sealant - LH LABOUR To remove and refit LH quater glass to facilitates the repairs To transfer LH front door interior mechanism and glass to new door To check and rectify wiring system To panel beat and straighten LH front fender inner panel, LH front chassis frame, LH front door pillar, to cut and weld LH front wheel house extension member, including replacement of parts and align where necesary, to refit and adjust the same To putty and spray paint on affected areas To compterise check wheel alignment 1 40.00 1 80.00 1 1,800.00 1 1,500.00 1 1,500.00	Front quater glass sealant - LH 1 40.00 LABOUR To remove and refit LH quater glass to facilitates the repairs To transfer LH front door interior mechanism and glass to new door To check and rectify wiring system To panel beat and straighten LH front fender inner panel, LH front chassis frame, LH front door pillar, to cut and weld LH front wheel house extension member, including replacement of parts and align where necesary, to refit and adjust the same To putty and spray paint on affected areas To compterise check wheel alignment 1 120.00 3,730.00 TOTAL ADD GST @ 8% 1 40.00 40.00 40.00 80.00 80.00 80.00 1,800.00 1,800.00 1,800.00 1,500.00 3,730.00

SINGAPORE DOLLAR THIRTEEN THOUSAND FIVE HUNDRED SEVEN AND CENTS FIFTY-SIX ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

FAX:

79, ROBINSON ROAD #09-01

SINGAPORE 068897

CLAIM TYPE : OWN DAMAGE ACCIDENT DATE : 02/04/2023

ATTN: MOTOR CLAIMS DEPT

YOUR REF NO :

NO

: QUOT202304-000028(00)

DATE

ESTIMATE

: 12/04/2023

POLICY NO

: SP2003902365

VEH REG NO : GBL5879L

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323891533

ENGINE NO

: 65195035425360

REG. DATE : 2021

Estimate Repair Cost to Vehicle No: GBL5879L

	Description	Quantity	Ur	nit Price	Amount	
1 2	SUPPLEMENTARY PARTS Support panel holder - LH Front fender signal lamp - LH	1 1 1	mil em	23.00 22.00 190.00	23.00 22.00 190.00)]
3		1	cm	118.00	118.00	_
				Add 10%	35.30 388.30	
		A	TO GST (OTAL 2 8%	S\$ 388.30 31.06	
			GRAND T	OTAL	S\$ 419.36	

SINGAPORE DOLLAR FOUR HUNDRED NINETEEN AND CENTS THIRTY-SIX ONLY

Parts: \$ 5,337.20 SN: 55.00

2,020.00

388.30

900.00 6,900.50

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE