



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

Not Notched
Heavy Bk paint

ATTN : MOTOR CLAIMS DEPT

TEL :

FAX :

EXTRA

YOUR REF NO :

13/4/23 9days

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 02/04/2023

ESTIMATE

NO : QUOT202304-000028(00)

DATE : 12/04/2023

POLICY NO : SP2003902365

VEH REG NO : GBL5879L

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323891533

ENGINE NO : 65195035425360

REG. DATE : 2021

Estimate Repair Cost to Vehicle No : GBL5879L

Description	Quantity	Unit Price	Amount
		SG	SG
PARTS			
1 Bonnet	<i>bent</i> 1	950.00	<i>B1</i> 950.00 ✓
2 Bonnet hinges - RH / LH	<i>old?</i> 2 ✓ <i>NLSB</i>	85.00	✓ 170.00 ✓
3 Bonnet lock	1	115.00	115.00 7 ✓
4 Bonnet catch <i>bent</i>	1	45.00	<i>R</i> 45.00 * ✓
5 Bonnet pull handle	1	98.00	98.00 7X
6 Bonnet cable	1	48.00	48.00 7 ✓
7 Support panel	1	325.00	<i>CDM</i> 325.00 ✓
8 Support panel top garnish	1	78.00	<i>CDM</i> 78.00 ✓
9 Support panel top bracket - RH / LH	1	23.00	<i>CDM</i> 23.00 7 ✓
10 Brace panel <i>bent</i>	1	88.00	<i>R</i> 88.00 * ✓
11 Headlamp assy - LH	1	580.00	<i>B2</i> 580.00 ✓
12 Front bumper	1	780.00	<i>CDM</i> 780.00 ✓
13 Front bumper reinforcement	1	620.00	<i>R</i> 620.00 X
14 Front bumper side retainer - LH	1	58.00	<i>CDM</i> 58.00 ✓
15 Front bumper inner carrier - LH	1	115.00	<i>CDM</i> 115.00 ✓
16 Front bumper centre logo	1	92.00	<i>Me</i> 92.00 ✓
17 Front bumper support - LH	1	<i>100</i> 58.00	<i>mi's</i> 58.00 ✓
18 Support panel side sponge - LH	1	24.00	<i>mi's</i> 24.00 ✓
19 Front bumper holder - LH	1	24.00	<i>mi's</i> 24.00 ✓
20 Front bumper lower frame	1	226.00	226.00 7
21 Front bumper under cover	1	112.00	112.00 7
22 Front grille inner support	1	480.00	480.00 7
23 Front fender - LH	1	590.00	<i>B1</i> 590.00 ✓
24 Front fender wheel house extension member- LH	1 <i>480</i>	780.00	<i>B1</i> 780.00 ✓
25 Front fender inner shield - LH	1	125.00	<i>CDM</i> 125.00 ✓
26 Front fender inner shield cover - LH	1	30.00	<i>me</i> 30.00 ✓
27 Front fender rail - LH	1	12.00	<i>mi's</i> 12.00 ✓
28 Front fender - LH	1 <i>Repair</i>	1,050.00	1,050.00 X
29 Front door hinges - LH	2	112.00	<i>R</i> 224.00 X
			7,970.00
			Add 10% 742.00
			8,712.00
SPECIAL NET			
30 Front door "company" sticker	1	25.00	<i>me</i> 25.00 ✓



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/08 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD
79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT
TEL : FAX :

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 02/04/2023

ESTIMATE

NO : QUOT202304-000028(00)
DATE : 12/04/2023
POLICY NO : SP2003902365
VEH REG NO : GBL5879L
MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR
CHASSIS NO : W1V44760323891533
ENGINE NO : 65195035425360
REG. DATE : 2021

Estimate Repair Cost to Vehicle No : GBL5879L

Description	Quantity	Unit Price	Amount
		S\$	S\$
31 Front quarter glass sealant - LH	1	40.00	40.00
			65.00
LABOUR			
32 To remove and refit LH quarter glass to facilitates the repairs	1	80.00	80.00
33 To transfer LH front door interior mechanism and glass to new door	1	150.00	150.00
34 To check and rectify wiring system	1	80.00	80.00
35 To panel beat and straighten LH front fender inner panel, LH front chassis frame, LH front door pillar, to cut and weld LH front wheel house extension member, including replacement of parts and align where necessary, to refit and adjust the same	1	1,800.00	1,800.00
36 To putty and spray paint on affected areas	1	1,500.00	1,500.00
37 To computerise check wheel alignment	1	120.00	120.00
			3,730.00
TOTAL			S\$ 12,507.00
ADD GST @ 8%			1,000.56
GRAND TOTAL			S\$ 13,507.56

SINGAPORE DOLLAR THIRTEEN THOUSAND FIVE HUNDRED SEVEN AND CENTS FIFTY-SIX ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 02/04/2023

ESTIMATE

NO : QUOT202304-000028(00)

DATE : 12/04/2023

POLICY NO : SP2003902365

VEH REG NO : GBL5879L

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : W1V44760323891533

ENGINE NO : 65195035425360

REG. DATE : 2021

Estimate Repair Cost to Vehicle No : GBL5879L

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Support panel holder - LH	1	23.00	23.00
2 Front fender signal lamp - LH	1	22.00	22.00
3 Front wheel rim - LH	1	190.00	190.00
4 Oil dipstick tube	1	118.00	118.00
			353.00
		Add 10%	35.30
			388.30
TOTAL			S\$ 388.30
ADD GST @ 8%			31.06
GRAND TOTAL			S\$ 419.36

SINGAPORE DOLLAR FOUR HUNDRED NINETEEN AND CENTS THIRTY-SIX ONLY

Parts : \$ 5,337.20
SN : 55.00
Labour : 2,020.00
Supp : 388.30
XS \$ 7,800.50
900.00
8% \$ 6,900.50
552.04
\$ 7,452.54

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE