



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD
79, ROBINSON ROAD #09-01
SINGAPORE 068897

TEL : 67143369 FAX :
ATTN: MOTOR CLAIMS DEPT

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 02/04/2023

TAX INVOICE

NO : AR202306-0001
CLAIM NO : QUOT202304-000028(01)
DATE : 01/06/2023
POLICY NO : SP2003902365
VEH REG : GBL5879L
MAKE/MODEL : MERCEDES BENZ VITO 114
CDI PANEL VAN LONG AT
ABS 5DR
CHASIS NO : W1V44760323891533
ENGINE NO : 65195035425360
REG. DATE : 2021

Final Repair Cost to Vehicle No : GBL5879L

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	950.00	950.00
2 Bonnet hinges - RH / LH	2	85.00	170.00
3 Bonnet lock	1	115.00	115.00
4 Bonnet catch	1	45.00	45.00
5 Bonnet cable	1	48.00	48.00
6 Support panel	1	325.00	325.00
7 Support panel top garnish	1	78.00	78.00
8 Support panel top bracket - RH / LH	1	23.00	23.00
9 Support panel holder - LH	1	23.00	23.00
10 Brace panel	1	88.00	88.00
11 Headlamp assy - LH	1	580.00	580.00
12 Front bumper	1	780.00	780.00
13 Front bumper side retainer - LH	1	58.00	58.00
14 Front bumper inner carrier - LH	1	115.00	115.00
15 Front bumper centre logo	1	92.00	92.00
16 Front bumper support - LH	1	100.00	100.00
17 Front bumper side sponge - LH	1	24.00	24.00
18 Front bumper holder - LH	1	24.00	24.00
19 Front fender - LH	1	590.00	590.00
20 Front fender wheel house extension member- LH	1	480.00	480.00
21 Front fender inner shield - LH	1	125.00	125.00
22 Front fender inner shield cover - LH	1	30.00	30.00
23 Front fender rail - LH	1	12.00	12.00
24 Front fender signal lamp - LH	1	22.00	22.00
25 Front wheel rim - LH	1	190.00	190.00
26 Oil dipstick tube	1	118.00	118.00
			5,205.00
		Add 10%	470.50
			5,725.50



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

TEL : 67143369

FAX :

ATTN: MOTOR CLAIMS DEPT

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 02/04/2023

TAX INVOICE

NO : AR202306-0001

CLAIM NO : QUOT202304-000028(01)

DATE : 01/06/2023

POLICY NO : SP2003902365

VEH REG : GBL5879L

MAKE/MODEL : MERCEDES BENZ VITO 114
CDI PANEL VAN LONG AT
ABS 5DR

CHASIS NO : W1V44760323891533

ENGINE NO : 65195035425360

REG. DATE : 2021

Final Repair Cost to Vehicle No : GBL5879L

Description	Quantity	Unit Price	Amount
		S\$	S\$
SPECIAL NET			
27 Front door "company" sticker	1	25.00	25.00
28 Front quarter glass sealant - LH	1	30.00	30.00
			55.00
LABOUR			
30 To remove and refit LH quarter glass to facilitates the repairs	1	40.00	40.00
31 To check and rectify wiring system	1	20.00	20.00
32 To panel beat and straighten LH front fender inner panel, LH front chassis frame, LH front door pillar, to cut and weld LH front wheel house extension member, including replacement of parts and align where necessary, to refit and adjust the same	1	1,100.00	1,100.00
33 To putty and spray paint on affected areas	1	800.00	800.00
34 To computerise check wheel alignment	1	60.00	60.00
			2,020.00

AMOUNT: S\$ 7,800.50

LESS EXCESS: S\$ 900.00

TOTAL: S\$ 6,900.50

ADD GST @ 8%: S\$ 552.04

GRAND TOTAL: S\$ 7,452.54

SINGAPORE DOLLARS SEVEN THOUSAND FOUR HUNDRED AND FIFTY-TWO AND CENTS FIFTY-FOUR ONLY

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE