

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En Au	itomol	bile CS3/ASM22000900/wp3
	AXA INSURANCE		Re		CSS/ASIVIZZ000900/Ety3
	8 SHENTON WAY				-25/01/2022 10/04/2023
			Co	ode:	ASM
	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	EK 9988Z	Veh. Inspected		FBR 7104U
	Policy No.		Coverage (\$)		0.00
	Claim No.	S2M03RJQ	Excess (\$)		0.00
	Assign From _{HEN}	G XINYI (SEAH ONG)	Assign Date		25/01/2022 10/04/2023
			culars & Condition		
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.	Colour			
	Odometer	Steering Modification			
	Brakes				
	General				
3.		Condit	ions of Tyres		
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
	Description of Damages				
j.	General Information				
	Accident Date	17/01/2022	Inspection Date		26/01/2022
	Survey held at	BIKERS AVENUE PTE LTD	•		
		NO 1 BUKIT BATOK CRESCENT #02-58 WCEGA PLAZA SINGAPORE 658064			
ia.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				