AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

5. REMARKS

Market Value:

Na

Salvage Value:

Na

Repair Limit:

Na

Estimated Amount:

\$6,032.90

Adjusted Amount:

\$4,420.10

F' 'al Adjusted Sum:


\$4,200.00

Estimated Repair Days:

8 days

Date of Completion :

13-Apr-2022



Pursuant to your instruction, we have $\underline{\text{\bf NOT AUTHORISED}}$ repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

ASSESSMENT REPORT FOR VEHICLE NO. FBR 7104 U

PARTS (LIST ITEMS)

*				Workshop's	Our
Qty	Description		Condition	Estimate	Assessment
1-	FRONT WIND SHIELD		Cracked	320.00	320.00
1	FRONT COVER SET		Cracked	480.00	480.00
1	FRONT HEAD LAMP ASSY		Cracked	582.00	582.00 🗸
1	FRONT HEAD LAMP STAY		Bent	165.00	nn 165.00 X
1	FRONT HEAD LAMP COVER		Cracked	188.00	188.00 🗸
1 2	FRONT SIDE SIGNAL LAMP L/R (RH)		Cracked	242.00	121 🗸 242.00
2	FRONT BODY COWLING L/R		Cracked	420.00	420.00 🗸
2	FRONT SIDE AIR INTAKE GARNISH L/R		Cracked	188.00	nn 188.00×
1	FRONT FORK ASSY		Repair	822.00	nn 🕝 🗙
	FRONT FENDER		Cracked	268.00	268.00
1	FRONT WHEEL		Repair	320.00	nn - X
1	FRONT WHEEL SHAFT		Bent	40.00	nn 40.00 🗙
1	FRONT WHEEL BEARING - SET		Jammed	65.00	nn 65.00 X
1	SIDE LH LEG SHIELD GARNISH		Repair	282.00	nn - X
		2379		4,382.00	2,958.00
		-10%	Less 5% discount	219.10	147.90
		2141.10	Parts Total:	4,162.90	2,810.10

ALON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874 Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

ASSESSMENT REPORT FOR VEHICLE NO. FBR 7104 U

SPECIAL NETT ITEMS

1 FRONT NUMBER PLATE STICKER FRONT FOG LAMP L/R - SET 1

Necessary Cracked

20.00

20.00 🗸

300.00 200

300.00

220

Special Nett Total:

320.00

Workshop's

Estimate

320.00

Our

Assessment

50.00 🗸

80.00

LABOUR

Description Towing charge. 1 Check wiring system and light. 2 3 Wheel ailgnment.

30 100.00 80.00 100.00 50 80.00

Fork ailgnment.

Labour for repair and replace parts.

The workshop has agreed to undertake the repair cost of

1,550.00 Labour Total: 1,290.00

100.00 50

50.00

TOTAL (PARTS & LABOUR) \$

6,032.90 4,420.10

1,200.00 300 1,000.00

480

2841.10

3 days

L/S - 2272.88

= 2250

the final adjusted Sum contract amount is \$4,200.00

(SINGAPORE DOLLARS FOUR THOUSAND TWO HUNDRED ONLY)



Amas Ong Automobile Assessor