

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23003795/TQY3Q2**Date:** 12/06/2023**REFERENCE**

Insured/Claimant:	GAN HENG	Policy No:	SP2004947004-01		
Date of Loss:	07/04/2023	Nature of Claim:	OD	Claim No:	202332007162

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNJ7626E	Engine No:	DJH032541
Make & Model:	VOLKSWAGEN ARTEON, 2.0 R-LINE (A)	Chassis No:	WVWZZZ3HZJE507241
Reg. Date:	14/06/2018 (Man. Year: 2017)	Odometer:	33650 km
Colour:	Maroon		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Yes

CONDITION OF TYRES

Front Tyre Size:	245/35 R20	Rear Tyre Size:	245/35 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,480.72	3,480.72	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	3,130.00	1,820.00	36.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,430.72	6,610.72	1,820.00	21.59
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	7,830.72	6,010.72	1,820.00	23.24
+ GST 8.00/8.00% (S\$)	626.46	480.86	145.60	23.24
Nett Amount (S\$)	8,457.18	6,491.58	1,965.60	23.24

INSPECTION

Date of Assignment:	11/04/2023	
Date Inspected:	13/04/2023	Inspected At: Volkswagen Group Singapore Pte Ltd (tuas) (HQ) 17 Tuas Ave 9 Singapore 639197
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 09 Jun 2023)**Parts:** 143 VOLKSWAGEN ARTEON 2.0 R-LINE (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SNJ7626E)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FLAP HINGE LH	Bent	312.47 FS	*312.47 FS
2	1		*FLAP HINGE	Bent	312.47 FS	*312.47 FS
3	2		*ACTIVATOR FOR PEDESTRIAN	Bent	179.90 FS	*179.90 FS
4	1		*CLIP (2 PCS)	Necessary	3.95 FS	*3.95 FS
5	1		*FOAM INSERT	Deformed	112.95 FS	*112.95 FS
6	1		*PRESSURE SENSOR	Activated	157.33 FS	*157.33 FS
7	1		*RADIATOR GRILLE WITH CHRO	Chipped	1,135.55 FS	*1,135.55 FS
8	1		*V/W SIGN BLACK /BRIGHT CHRO	Missing	346.46 FS	*346.46 FS
9	1		*NUMBER PLATE	Bent	80.00 FS	*80.00 FS
10	1		*AIR DUCT	Cracked	32.26 FS	*32.26 FS
11	1		*IMPACT BEAM (REINFORCEMENT)	Bent	802.94 FS	*802.94 FS
12	1		*POP-RIVET (4 PCS)	Necessary	4.44 FS	*4.44 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	3,480.72	3,480.72
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	200.00	0.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	360 CAMERA CALIBRATOR	New	560.00	560.00
4	RADAR SENSOR CALIBEATION	New	560.00	560.00
5	LABOUR	New	1,680.00	1,120.00
6	SPRAY PAINTING	New	1,590.00	530.00
			Gross Labour Cost (S\$)	4,950.00
				3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >