

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Not Authorised

1/1 Rep &

Repair After Paint

5 days

TP CHINA  
(LLK)

Vehicle Insured : PC 6958 S  
Accident Date : 29-Mar-2023

No. : 32861

Date : 30-Mar-2023

Our Ref : 023176 (CHINA) / JADE

PAGE : 1

GILL5 ENTERPRISE  
Singapore

ESTIMATED COST OF REPAIR FOR KIA CARENS (1685CC) (2017) SLS3027L

1 pc rear bumper			CM	477.00	—
1 pc rear bumper lower (black)			CM	189.00	—
1 pc rear bumper lower diffuser (silver)				320.00	?
1 pc rear bumper tow cover			nu	8.00	—
1 pc RH rear bumper side retainer			nu	35.00	—
1 pc rear bumper reinforcement				367.00	?
1 pc rear bumper reinforcement bracket				159.00	?
3 pcs rear bumper lower stay holder	@ S\$ 6.00	18.00			?
2 pcs rear bumper upper stay holder	@ S\$ 6.00	12.00			?
1 pc rear bumper undercover			nu	24.00	X
8 pcs rear bumper clips	@ S\$ 4.00	32.00	nu		—
1 pc RH rear bumper fog lamp			nu	115.00	—
1 pc RH rear bumper parking sensor outer				177.00	?
4 pcs rear bumper parking sensor bracket	@ S\$ 4.00	16.00	nu		—
1 pc rear end panel			nu	365.00	?
1 pc RH taillamp			nu	770.00	—
1 pc tailgate			nu	1,088.00	—
1 pc RH tailgate lamp			nu	773.00	—
1 pc tailgate 'CARENS' emblem			nu	36.00	—
1 pc tailgate 'CRDi' emblem			nu	42.00	—
1 pc tailgate logo			nu	86.00	—
1 pc tailgate weatherstrip			nu	131.00	X
				5,240.00	
Less 10% :				-524.00	
					4,716.00

Vehicle Insured : PC 6958 S  
Our Ref : 023176

Page : 2  
No. : 32861

1 pc tailgate glass sealant  
1 pc tailgate glass damping seal

40.00 sn ✓  
20.00 sn ✓

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

500.00 ✓

To remove and refit reverse sensor  
assy.

60.00 501

To remove and refit rear windscreen  
glass and conduct water leak test

120.00 ✓

To transfer tailgate's fittings

80.00 601

To putty and respray on affected  
portions.

800.00 6001

To focus taillamps. To check rear  
wiring and lighting operation.

30.00 201

Total : S\$ 6,366.00

Singapore Dollars SIX THOUSAND THREE HUNDRED  
AND SIXTY SIX Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: